



Photo 5: View of the air conditioning units, bunded oil tank, generator, electricity substation, gas house and water tanks immediately north of the clubhouse



Photo 6: View of the bunded oil tank and sodium hypochlorite bottles immediately north of the clubhouse





Photo 7: View of the water tanks immediately north of the clubhouse



Photo 8: View of the electricity substation immediately north of the clubhouse





Photo 9: View south-east of the golf course from the clubhouse



Photo 10: View south-west of the car park with the maintenance building beyond, from the clubhouse





Photo 11: Plant room located in the south-east corner of the clubhouse buildings



Photo 12: Bunded tank and gas bottles located in the south-west corner of the clubhouse buildings





Photo 13: Bunded oil tank located immediately north of the maintenance building



Photo 14: Sodium hypochlorite bottles located immediately north of the maintenance building





Photo 15: Waste and materials storage area immediately south of the maintenance building



Photo 16: Bunded oil tank and fertiliser bottles immediately south of the maintenance building





Photo 17: View south along the western boundary of material stockpiles, with a recently constructed building in the foreground.



Photo 18: View south of the artificial swale excavated into the bedrock located in the south-west corner





Photo 19: View north-east of a concrete slab of assumed former buildings with the disused driving range beyond



Photo 20: View west of steel drums and waste materials within the WIG Engineering land, adjacent to the site boundary





Photo 21: View west along the northern boundary of steel drums and Tanora Cottage beyond



Photo 22: View east along the northern boundary of the golf course from the north-west corner





4th Floor
6 Devonshire Square
London
EC2M 4YE

wsp.com