

**Project** 

Project Name: The Bungalow White Post Road Bodicote OX15 4BN Post

Repair

Project Description: Post Repair CCTV Survey

**Project Date:** 21/11/2022






Assured Drainage 49 Beaconsfield Road, Banbury Tel. 07566 221 736

### **Table of Contents**

Project Name	Project Number	Project Date
The Bungalow White Post Road Bodicote OX15 4BN Post Repair		21/11/2022

Project Information	P-1
Section: 1; MH02 > MH01 (MH02X)	1





49 Beaconsfield Road, Banbury Tel. 07566 221 736

# **Project Information**

Project Name	Project Number	Project Date
The Bungalow White Post Road Bodicote OX15 4BN Post Repair		21/11/2022

### Client

Company: Debbie Whitford Department: The Bungalow Street: White Post Road

**Town or City:** Bodicote **Post Code:** OX15 4BN

#### Contractor

**Company:** Assured Drainage **Street:** 49 Beaconsfield Road

Town or City: Banbury
County: Oxfordshire
Post Code: OX16 9EP
Phone: 07566 221 736



#### **Assured Drainage**

49 Beaconsfield Road, Banbury Tel. 07566 221 736

Ura		Inta	rmai	·IAN
Pro		HHO	ши	ICH
	,			

Project Name	Project Number	Project Date
The Bungalow White Post Road Bodicote OX15 4BN Post Repair		21/11/2022

#### **Project Summary**

As the re-round did not fully reform the drains as required the decision was taken to excavate the worst of the deformed drain. During the excavation roots of 100mm diameterwere the cause of the deformation in the drainage. Furthermore there were several roots in the region of 75mm causing deformation to the drain. On inspection of the drain off boundary to the village hall ic cover root intrusion and cracked clay pipe have been observed. The roots have been removed but the drain remains damaged. This may cause future issues.



Assured Drainage 49 Beaconsfield Road, Banbury Tel. 07566 221 736

# **Project Information**

	•	
Project Name	Project Number	Project Date
The Bungalow White Post Road Bodicote OX15 4BN Post Repair		21/11/2022

Project Notes	
Attend site to re-round and reline drains	



## Section Inspection - 14/11/2022 - MH02X

				•			
Section	Inspection	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
1	1	14/11/22	16:53	DEBBIE WHITFORD	No Rain Or Snow	No	MH02X
Оре	erator	Veh	icle	Camera	Preset Length	Legal Status	Alternative ID
SH	AWN	Not Sp	ecified	Not Specified	Not Specified	Not Specified	1


Town or Village:	Bodicote	Inspection Direction:	Downstream	Upstream Node:	MH02
Road:	White Post Road	Inspected Length:	11.40 m	Upstream Pipe Depth:	0.410 m
Location:	Gardens	Total Length:	11.40 m	Downstream Node:	MH01
Surface Type:		Joint Length:	0.00 m	Downstream Pipe Depth:	0.730 m
Use.	Foul	•	Pine Shape	Circular	

ipe Shape: Type of Pipe: Gravity drain/sewer Dia/Height: 100 mm

Year Constructed: Pipe Material:

Fibreglass reinforced pipe Flow Control: No flow control Lining Type: Cured in place lining

Inspection Purpose: Post completion inspection of repairs or renovations **Lining Material:** No Lining



Construction Features					Misc	ellaneous Fea	tures		
	Structural Defects			Service & Operational Observations					
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Finish node type, manhole, reference number:

MHF

MH01


11.40

MH01 Depth: 0.73 m



#### **Section Pictures - 14/11/2022 - MH02X**


Section	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
1	Downstream	MH02X	DEBBIE WHITFORD	THE BUNGALOW



221114\_1652A-Survey.jpg, 00:00:00, 0.04 m Water level, 0% % of the vertical dimension



221114\_1652B-Survey.jpg, 00:00:29, 6.19 m Connection other than junction, at 09 o'clock, diameter: 100



221114\_1653A-Survey.jpg, 00:00:57, 11.40 m Finish node type, manhole, reference number: MH01