

25.



10.09.14 Eastern view along the south of the site, stockpile storage area

26.



24.09.14 View to the south of the site, Agg-SW visible in the background

27.



24.09.14 Removal of hard-standing exposed natural soils across the south-west of the site

28.



24.09.14 Aggregate stockpile Agg-W located along the western boundary

29.



24.09.14 Remediation earthworks completed in the north-west corner

30.



24.09.14 Aggregate stockpile Agg-SW

31.



24.09.14 Aggregate stockpile Agg-SE

32.



07.10.14 Western view across the southern face of retained building 488

33.



07.10.14 Northern view along the western side of the site, exposed natural strata following hard-standing strip

34.



07.10.14 Temporary stockpiles of hydrocarbon waste generated from UST remediation temporarily stockpile (background)

35.



07.10.14 Protected trees in the south of the site

36.



07.10.14 Stockpile storage area in the south with tarmac, subsoil and concrete awaiting processing

37.



22.10.14 – View of the centre of the site with building 465 visible in the background (to be retained)

38.



22.10.14 – Central view of the site, natural soils exposed following strip of hard-standing

39.



22.10.14 – Waste processing area in the north of the site, waste awaiting off-site disposal/recycling

40.



22.10.14 - Waste processing area in the north of the site, waste awaiting off-site disposal/recycling

41.



12.01.15 – Eastern view to the centre of the site, building 465 which is to be retained is visible in the background

42.



12.01.15 - Southern view from the centre of the site, stockpile Agg-SW visible in background

43.



12.01.15 – Western view across the site following completion of earthworks, stockpile Agg-W visible in the background

44.



12.01.15 – Southern view down the centre of the site, northern face of building 465 visible.

45.



12.01.15 – Eastern view across the north of the site following completion of earthworks, D1B:Area 1 visible in the background

46.



12.01.15 – Temporary stockpile of waste wood which has undergone processing (chipping) awaiting removal off-site

47.



12.01.15 – North-west corner of the site being utilised as a brick store following completion of earthworks

48.



12.01.15 - North-west corner of the site being utilised as a brick store following completion of earthworks. Retained road which not remediated.

APPENDIX B

Formation Level Validation Photo Record

1.



05.12.13 - Cover Validation: Plot 459-SS1

2.



05.12.13 - Cover Validation: Plot 459-SS2

3.

No Photo

05.12.13 - Cover Validation: Plot 459-SS3

4.



18.08.14 - Cover Validation: D1B-SS1

5.



18.08.14 - Cover Validation: D1B-SS5

6.



18.08.14 - Cover Validation: D1B-SS6

7.



18.08.14 - Cover Validation: D1B-SS7

8.



18.08.14 - Cover Validation: D1B-SS9

9.



18.08.14 - Cover Validation: D1B-SS13

10.



18.08.14 - Cover Validation: D1B-SS14

11.



18.08.14 - Cover Validation: D1B-SS15

12.



18.08.14 - Cover Validation: D1B-SS16

13.




18.08.14 - Cover Validation: D1B-SS17

14.



18.08.14 - Cover Validation: D1B-SS18

15.



18.08.14 - Cover Validation: D1B-SS19

16.



18.08.14 - Cover Validation: D1B-SS20

17.



18.08.14 - Cover Validation: D1B-SS21

18.



18.08.14 - Cover Validation: D1B-SS22

19.



18.08.14 - Cover Validation: D1B-SS23

20.



18.08.14 - Cover Validation: D1B-SS24

21.



18.08.14 - Cover Validation: D1B-SS25

22.



18.08.14 - Cover Validation: D1B-SS26

23.



18.08.14 - Cover Validation: D1B-SS27

24.



18.08.14 - Cover Validation: D1B-SS28