

**PROPERTY HISTORY**  
**Cedar Lodge North Side Steeple Aston Bicester**

**Development Control Applications (DC)**

Application Reference	Development	Status	Open Date / Closed Date
00/00930/F	Erection of an oak framed conservatory at rear	PER	3 May 2000 / 5 July 2000
00/00932/LB	Demolition of existing bay window/door to allow erection of oak framed conservatory at rear	PER	3 May 2000 / 6 July 2000
01/00075/TCA	Reduce weight on heavy branches of Black Pine and Holm Oak trees	TPO	11 January 2001 / 17 May 2001
05/00763/TCA	Fell 1 No. Ash	PER	15 April 2005 / 23 May 2005
05/01272/TCA	Reduce Crown of 3 No. Willows by 30-40% and Fell 4 No. Ash	PER	27 June 2005 / 12 August 2005
08/02413/TCA	Fell 3 no Acacia Trees	PER	21 November 2008 / 31 December 2008
17/00030/TCA	T1, T2 x Ash - Fell and replace with young trees more suitably positioned in the garden	PER	20 January 2017 / 21 February 2017
17/00185/TCA	G1- Yew, remove to ground level x1 upright A-symmetrical tree plus x2 horizontal stems in favour of adjacent stand alone Mature Yew Tree.	PCO	30 May 2017 /

**Development Monitoring Applications (DM)**

Application Reference	Development	Status	Open Date / Closed Date
-----------------------	-------------	--------	-------------------------

**Building Control Applications (BC)**

Application Reference	Development	Status	Open Date / Closed Date
94/10954/OTHBN	Alterations and drainage	BNA	28 June 1994 / 6 July 1994
CP/NICEIC/04178/2015	Replacement consumer unit	BCO	12 January 2011 /