


Front Step Restoration

Images showing the current condition of the steps



The flag stones are broken and need replacement with stone.





The rail is bent and needs repair.



Many of the bricks have blown and new bricks (of the same style and colour) need putting in their place. The front facing bricks may be replaced with stone for long term durability.



The side bricks are blown.