


- The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before proceeding with the works.
 - Where an item is covered by drawings to different scales the larger scale drawing is to be worked to.
 - Do not scale drawing. Figured dimensions to be worked to in all cases.

CDM Regulations 2007

All current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environmental Assessment Record.



date	rev	revison/author/checker

client

purpose of Issue
PLANNING

project
Bicester Phase 384

drawing
Drawing Location Plan

drawing no	AL5695/2100	rev	-
drawn	KJ	checked	AGF
scale @ A1/A3	1:1000	date	09.10.2015