


The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before proceeding with the works. Where an item is covered by drawings to different scales the larger scale drawing is to be worked to.

Do not scale drawing. Figured dimensions to be worked to in all cases.
CDM REGULATIONS 2015. All current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environment Assessment Record

All intellectual property rights reserved.



Key

Proposed Gable Windows

Rev	Date	Description	Dwn	Ckd
A	30/10/17	Gable windows to plot 56 removed	KK	SW
/	19/10/17	First Issue ...Planning	KK	SW

Bicester Eco Town - Phases 3&4

Gable Window Locations

AA2699C(3)/2007 **A**
PLANNING

Drawn SW Checked RS Date OCT 2017 Scale @ A1 1:100