

01 Verge Detail - Condition 1

Type 1 - Bekstone / Render





KEY ELEVATION
TYPE - 1



ELEVATION OF VERGE - INTERFACE OF BRICKS/ BRICK SLIPS

Dashed line indicates back of corresponding OSB board in render/ spandrel panel condition - refer to detail 02

Dashed line indicates back of corresponding OSB board in render/ blockwork condition - refer to detail 01



02 Verge Detail - Condition 2

Type 1 - Bekstone / Render (5 bed dwellings only)





KEY ELEVATION
TYPE - 1

WILLMOTT DIXON HOUSING

REVIEWED

STATUS

PRELIMINARY

FOR COMMENT A

FOR CONSTRUCTION B

SIGNED C

DATE

CDM Regulations 2007

ALL current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environmental Assessment Record.

notes

- The contractor is responsible for checking dimensions, tolerances and the accuracy of setting out before proceeding with the works. Any discrepancies to be verified with the Architect before proceeding with the works.
- Where an item is covered by drawings to different scales the larger scale drawing is to be worked to.
- Do not scale drawing. Figured dimensions to be worked to in all cases.

date	rev	revision/author/checker
22-12-2014	B	Amended to WDH comments; cf/ rs
15-01-2014	A	Details updated; JW/MDB
09-12-2013	-	First issue; JW/MDB

purpose of issue
CONSTRUCTION

project
BICESTER ECO TOWN EXEMPLAR SITE

drawing
DETAILS
TYPE 1 DWELLINGS
[Bekstone / Render] Sheet 7

drawing no
AA2699C 6.1 036
rev B

drawn TL
checked MDB
scale @ A1 1:5
date Nov 2013

PRP Architects © 10 Luke Street London EC1A 9HP
T +44 (0)20 7253 1200
F +44 (0)20 7253 1201
lon.prp@prparchitects.co.uk