

- The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before

- Where an item is covered by drawings to different scales the larger scale

- Do not scale drawing. Figured dimensions to be worked to in all cases.

ALL current drawings and specifications for the project must be read in

conjunction with the Designer's Hazard and Environmental Assessment Record.

proceeding with the works.

drawing is to be worked to.

CDM Regulations 2007

NORTH

date rev revision/author/checker

purpose of issue

PLANNING

BICESTER ECO TOWN
EXEMPLAR SITE

PROPOSED DETAILS
TYPE 1 DWELLINGS
[Brickwork / Render]

drawing no
AA2699C/6.1/010

drawn JW checked MB

scale @ A1 1:20 & 1:10 date

PRP Architects ©
10 Lindsey Street
Smithfield
London
EC1A 9HP
T +44 (0)20 7653 1200
F +44 (0)20 7653 1201
lon.prp@prparchitects.co.uk



JAN 2013