

The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before proceeding with the works.

- Where an item is covered by drawings to different scales the larger scale drawing is to be worked to. - Do not scale drawing. Figured dimensions to be worked to in all cases.

CDM Regulations 2007

ALL current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environmental Assessment Record.

Beckstone

Timber & Render

Timber & Beckstone

19-10-15 - First Issue. Planning date rev revision/author/checker

A2 Dominion

purpose of issue

Planning - For Approval

Bicester Eco Town

Phases 3&4

Materials diagram

AA2699(3)/2004

date Oct 2015 scale @ A1/A3 1:1000

PRP Architects ©
10 Lindsey Street
Smithfield
London
EC1A 9HP
T +44 (0)20 7653 1200
F +44 (0)20 7653 1201
lon.prp@prparchitects.co.uk

