



notes

- The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before proceeding with the works.
- Where an item is covered by drawings to different scales the larger scale drawing is to be worked to.
- Do not scale drawing. Figured dimensions to be worked to in all cases.

CDM Regulations 2015

ALL current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environmental Assessment Record.

08-10-15 - First Issue. Planning

date	rev	revision/author/checker

purpose of issue  
Comment

project  
**Bicester Eco Town Phases 3&4**

drawing  
**Site Location Plan**

drawing no  
**AA2699(3)/2000**

drawn	SW	checked	SW
scale @ A1	1:2500	date	Oct 2015

PRP Architects G  
10 Lindsey Street  
Southfield  
London  
ECLA WPP  
T +44 (0)20 7653 1200  
F +44 (0)20 7653 1201  
lon.prp@prparchitects.co.uk



15/00134/NMA