



notes

- The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before proceeding with the works.
- Where an item is covered by drawings to different scales the larger scale drawing is to be worked to.
- Do not scale drawing. Figured dimensions to be worked to in all cases.

CDM Regulations 2015

ALL current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environmental Assessment Record.

08-10-15 - First Issue, Planning

date	rev	revision/author/checker

purpose of issue
Comment

project
**Bicester Eco Town
Phases 3&4**

drawing
Site Location Plan

drawing no AA2699(3)/2000	rev /
-------------------------------------	----------

drawn SW	checked SW
----------	------------

scale @ A1 1:2500	date Oct 2015
-------------------	---------------

PRP Architects ©
10 Lindsey Street
Smithfield
London
EC1A 9RP
T +44 (0)20 7653 1200
F +44 (0)20 7653 1201
lon.prp@prparchitects.co.uk

