



Zoomed in view showing replacement house (buildings to be removed shown with dashed red line)

Figure 10
Viewpoint photograph 1A
Footpath 348/7



Note: telegraph pole leans



Zoomed in view showing replacement house (buildings to be removed shown with dashed red line)

Figure 11
Viewpoint photograph 1B
Footpath 348/7



Zoomed in view showing replacement house (buildings to be removed shown with dashed red line)

Figure 12
Viewpoint photograph 2A
Bridleway 348/2



Zoomed in view showing replacement house (buildings to be removed shown with dashed red line)




View looking east along direction of travel

Figure 13
Viewpoint photograph 2B
Bridleway 348/2



Zoomed in view showing replacement house (buildings to be removed shown with dashed red line)

Figure 14
Viewpoint photograph 3
Bridleway 347/1



View showing replacement house (buildings to be removed shown with dashed red line)

Figure 15
Viewpoint photograph 4




Zoomed in view



View showing replacement house (buildings to be removed shown with dashed red line)

Figure 16
Viewpoint photograph 5
Footpath 347/2



Zoomed in view



View showing replacement house (buildings to be removed shown with dashed red line)

Figure 17
Viewpoint photograph 6
Traitors Ford Lane/SS63

Proposed
view before
tree planting



Year 1



Year 15



Figure 18
Sketch showing impact of planting on
viewpoint 1B (FP 348/7)

Proposed
view before
tree planting



Year 1



Year 15



Figure 19
Sketch showing impact of planting on
viewpoint 2B (BW 347/1)

Proposed
view before
tree planting



Year 1



Year 15



Figure 20
Sketch showing impact of planting
on viewpoint VP5 (FP 347/2)