

PROPERTY HISTORY**Temple Close Temple Mill Road Sibford Gower Banbury****Development Control Applications (DC)**

Application Reference	Development	Status	Open Date / Closed Date
09/00250/TCA	T1 - 1 x Black Walnut - Crown lift by 1m (trim tips)	PER	19 October 2009 / 2 December 2009
12/00145/TCA	T1 x American Walnut - Lift by 5m , 10% thin and deadwood T2 x Spruce - Fell T3 x Group of Prunus, Tilia and Fagus - Lift by 3m	PER	7 June 2012 / 18 July 2012
12/00338/TCA	FIVE DAY NOTICE T4 x Ash - Fell on the grounds of safety	PER	28 November 2012 / 29 November 2012
16/01261/F	Replacement of single storey extension to south elevation with new single storey extension; demolition of conservatory to the south elevation and erection of covered garden structure; addition of two canopy porches to the front doors to the south elevation; and the replacement of first floor windows to the east and west elevation and the existing glazed lantern to the roof.	PER	27 June 2016 / 20 October 2016
16/00307/TCA	T1 x Acer - 30% Crown reduction and Crown thin T2 x Sycamore - 30% Crown reduction and Crown thin	PER	25 October 2016 / 15 December 2016
17/00094/TCA	T3 x Willow - Fell and replace to mitigate risk of failure.	PCO	14 March 2017 /

Development Monitoring Applications (DM)

Application Reference	Development	Status	Open Date / Closed Date
-----------------------	-------------	--------	-------------------------

Building Control Applications (BC)

Application Reference	Development	Status	Open Date / Closed Date
94/10936/OTHFP	Temple Close Colony Road Sibford Gower Banbury Oxon Extension	FPA	3 March 1994 / 11 May 1994