

STRUCTURAL SOILS LTD

INSITU TESTING REPORT

Report No.	745612R.01(00)					
Date	26-May-2015	Contract	Green Lane	, Chesterton		
Client Address For the Atter	RSK Environmental Ltd Spring Lodge 172 Chester Road Helsby Cheshire WA6 0AR ttion of Michael	Lawson				
Order receive Testing Start Testing Com	ed	12-May-2015 19-May-2015 20-May-2015	5	Client Reference Client Order No. Instruction Type	313035 PO249498 Written	
Test(s) under	rtaken (Not UKAS Accredi	ted)				
3no. Insitu so	BR tests carried out at loca bakaway tests carried out at rtaken in the Laboratory			nt		
Environment	al conditions (if relevant)					
The results represent the ground conditions at the specified locations and depths at the time of testing.						
Test were und	Remaining samples will be reta ertaken on samples 'as receive interpretations expressed in th	d' unless otherwise	stated.		poratory.	gelof 13

Structural Soils Ltd 1a Princess Street Bedminster Bristol BS3 4AG Tel.0117 9471000 Fax.0117 9471004 e-mail justin.barrett@soils.co.uk

TESTING VERIFICATION CERTIFICATE

The test results included in this report are certified as:-

ISSUE STATUS: FINAL

In accordance with Structural Soils Ltd Laboratory Quality Assurance Manual, Issue 6, January 2010 all results sheets and summaries of results issued by the laboratory are checked by an approved signatory. This check will also involve checking of at least 10% of calculations for each test type to ensure that data has been correctly entered into the computer and calculated. The integrity of the test data and results are ensured by control of the computer system employed by the laboratory as part of the Software Verification Program as detailed in the Laboratory Quality Assurance Manual.

This testing verification certificate covers all testing compiled on or before the following datetime: **22/05/2015 16:02:07**.

Testing reported after this date is not covered by this Verification Certificate.

Approved Signatory Sam Handcock (Site Testing Manager)

Contract:



STRUCTURAL SOILS 1a Princess Street Bedminster Bristol BS3 4AG

Green Lane, Chesterton

745612

Job No:


AGS



Non standard test

Soakaway Test - Position ID : TP01

PLOT OF DEPTH OF WATER BELOW GROUND LEVEL AGAINST TIME



745612



Non standard test

Soakaway Test - Position ID : TP03

PLOT OF DEPTH OF WATER BELOW GROUND LEVEL AGAINST TIME

