

Envirocheck®

LANDMARK INFORMATION GROUP®


Large-Scale National Grid Data

Published 1994


Source map scale - 1:2,500

'Large Scale National Grid Data' superseded SIM cards (Ordnance Survey's 'Survey of Information on Microfilm') in 1992, and continued to be produced until 1999. These maps were the fore-runners of digital mapping and so provide detailed information on houses and roads, but tend to show less topographic features such as vegetation. These maps were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)



Historical Map - Segment A16



Order Details

Order Number: 154470925_1_1 Customer Ref: 70042711 National Grid Reference: 454880, 221230

Site Area (Ha): Search Buffer (m): 49.74 100


Site Details


Bicester Hotel Golf & Spa, Chesterton, BICESTER, OX26 1TE

Landmark

0844 844 9951 www.envirocheck.co.uk

A Landmark Information Group Service v50.0 26-Jan-2018 Page 9 of 11






Envirocheck®

LANDMARK INFORMATION GROUP®

Historical Aerial Photography Published 1999

This aerial photography was produced by Getmapping, these vertical aerial photographs provide a seamless, full colour survey of the whole of Great Britain

Historical Aerial Photography - Segment A16



Order Details

Order Number: 154470925_1_1
Customer Ref: 70042711
National Grid Reference: 454880, 221230

Site Area (Ha): Search Buffer (m): 49.74

Site Details

Bicester Hotel Golf & Spa, Chesterton, BICESTER, OX26 1TE

Landmark

••• INFORMATION GROUP

0844 844 9952 0844 844 9951 www.envirocheck.co.uk

A Landmark Information Group Service v50.0 26-Jan-2018 Page 11 of 11

Appendix D

ADDITIONAL INFORMATION





Pre-Desk Study Assessment	
Site:	Bicester Golf Course, Green Lane, Chesterton, Oxfordshire
Client:	WSP
Contact:	Ashley Gillan
Date:	8 th February 2018
Pre-WWI Military Activity on or Affecting the Site	None identified.
WWI Military Activity on or Affecting the Site	None identified.
WWI Strategic Targets (within 5km of Site)	The following strategic targets were located in the vicinity of the Site: Royal Flying Corps (RFC) Weston-on-the-Green. RFC Bicester. Military training areas. Transport infrastructure and public utilities.
WWI Bombing	None identified on the Site.
Interwar Military Activity on or Affecting the Site	None identified.
WWII Military Activity on or Affecting the Site	None identified.
WWII Strategic Targets (within 5km of Site)	The following strategic targets were located in the vicinity of the Site: Royal Air Force (RAF) Weston-on-the-Green. RAF Slade Farm. RAF Bicester. Military camps and training areas. Transport infrastructure and public utilities. Anti-invasion defences.
WWII Bombing Decoys (within 5km of Site)	None.
WWII Bombing	During WWII the Site was located in the Rural District (RD) of Ploughley, which officially recorded 278No. High Explosive (HE) bombs with a very low regional bombing density of 3.5 bombs per 405 hectares (ha). Readily available records have been found indicating that at least 4No. HE bombs fell in the
	immediate vicinity of the Site.
Post-WWII Military Activity on or Affecting the Site	None identified.
Recommendation	It is recommended that a detailed desk study is commissioned to assess, and potentially zone, the Unexploded Ordnance (UXO) hazard level on the Site.

This summary is based on a cursory review of readily available records. Caution is advised if you plan to action work based on this summary.

It should be noted that where a potentially significant source of UXO hazard has been identified on the Site, the requirement for a detailed desk study and risk assessment has been confirmed and no further research will be undertaken at this stage. It is possible that further indepth research as part of a detailed UXO desk study and risk assessment may identify other potential sources of UXO hazard on the Site.

Kind regards, Lucy

Dr Lucy Warwick

Researcher Zetica Limited Subject: RE: 13/01102/f - Bicester Golf and Country Club

Rebecca,

My records do not indicate contamination may affect this development. I recommend applying condition J16 or informative ZZ in case there is any unsuspected contamination found during the development.

Best regards,

Sean

Sean Gregory

Environmental Protection Officer Public Protection and Development Management Cherwell District Council

Appendix E

SITE PHOTOGRAPHS





Photo 1: View immediately north of the Clubhouse with air conditioning units and waste compactor





Photo 2: View immediately north of the Clubhouse with waste storage, propane bottles and steel barrels





Photo 3: View east of the golf course from the clubhouse with a drainage ditch in the foreground





Photo 4: View of the propane gas immediately north of the clubhouse

