

## **Outside Paint Restoration**

This photo shows the difference in the finishes between the front and back/sides of the building. These will not be changed. We are looking to restore the building to what it was using high quality paint.

The following images express the need for this work to be done. You can see the disrepair that the window frames and render are in.





