

**APPENDIX 2**  
**SITE WALKOVER PHOTOGRAPHS**

**22145**  
**Mawles Farm, Pound Lane**



Photograph A: Looking south at the yard with the L-shaped building beyond



Photograph B: Looking west at the open end of the L shaped building

**Site Photographs**

Scale: NTS

**Figure A2.1**



22145

Mawles Farm, Pound Lane



Photograph C: Looking south at the refuelling area, including fuel tank



Photograph D: Looking south at brick building attached to the L-shaped building

Site Photographs

Scale: NTS

Figure A2.2



22145

Mawles Farm, Pound Lane



Photograph E: Internal view of the brick building including a suspected water tank



Photograph F: Looking west from the southwest corner of the site within the lower ground loading bay

## Site Photographs

Scale: NTS

Figure A2.3



22145

Mawles Farm, Pound Lane



Photograph G: Looking northeast at the piggyery and bulging brick wall with modern storage barn beyond



Photograph H: Looking northeast at the modern storage barn

## Site Photographs

Scale: NTS

Figure A2.4



22145

Mawles Farm, Pound Lane



Photograph I: Looking south at the crack present within the open end of the L shaped building

## Site Photographs

Scale: NTS

Figure A2.5

