

client

#### **Tritax Symmetry Ltd and Siemens Healthineers**

project title

**Symmetry Park, North Oxford** 

drawing title

Landscape Strategy Plan


date 11 NOVEMBER 2021 drawn by drawing number edp2425\_d042a checked scale bar @ A2 QA RB



the environmental dimension partnership

Registered office: 01285 740427 - www.edp-uk.co.uk - info@edp-uk.co.uk

# Appendix EDP 3 Tree Protection Barrier on Scaffold 2.0m High (Extract from BS 5837:2012, Figure 2 'Protective Barrier')



- 2 Heavy gauge 2 m tall galvanized tube and welded mesh infill panels
- 3 Panels secured to uprights and cross-members with wire ties
- 4 Ground level
- 5 Uprights driven into the ground until secure (minimum depth 0.6 m)
- 6 Standard scaffold clamps

# Appendix EDP 4 Programme of Arboricultural Inputs

Phase	Activity	Extent of Input			
Pre-commencement	Pre-commencement	Developer/ACW to brief appointed arboricultural			
	tree works	contractor. A monitoring visit will be conducted to			
		check successful completion of tree works before			
		installation of protective barriers.			
	Installation of tree	The developer to monitor the installation of protective			
	protection measures	barriers to form Construction Exclusion Zone (CEZ)			
		ensuring distances and specification comply with			
		those specified in <b>Plan EDP 1</b> and <b>Appendix EDP 3</b> .			
Construction Phase	Monitor and maintain	Tree protection measures will be monitored and			
	tree protection	maintained by the appointed contractor throughout the			
	measures	construction phases. Any defects will be reported to the			
		developer and remedied by the appointed contractor.			
	Phased construction	The developer will monitor the health and condition of			
	tree inspection	the retained trees and identify any remedial works			
		after completion of each construction phase.			

## Appendix EDP 5 Example of Tree Protection Notice



#### TREE PROTECTION AREA!

THIS FENCING MUST BE MAINTAINED IN ACCORDANCE WITH THE APPROVED PLANS AND DOCUMENTS FOR THIS DEVELOPMENT

IF ANY DAMAGE TO OR BREACH OF THE TREE PROTECTION FENCING OCCURS PLEASE CALL:

01285 740 427



## Appendix EDP 6 Sample Site Inspection Record

Site				Date						
	Arboricultural Clerk									
				of Works (ACW)						
Developer			Planning Appl	ication Number						
Site Manager		Contact No.								
Notes and overview of today's ACW site visit										
	<del>-</del>									
Are any special works scheduled for coming build period?					Yes	No				
	orks schedule	d for comir	ng build period	?						
Give details										
Oamanal Owamilaw	and Obsales I	!-4.				V	l Nia			
General Overview and Checks List:						Yes	No			
Protective fencing all as approved?										
Was debris/storage/groundwork evident within CEZ? Was there any evidence of damage to trees?										
was there any evi	uence or dama	ge to trees	<u>(</u>							
Circus ad			Circus al							
Signed			Signed							
Name			Name							
Company			Company	+						
ACW for and on behalf of: Main Contractor for and on behalf of:										
Circulations		Nones		Contact Date	nilo					
Circulation: Name			Contact Deta	alis						
LPA Tree Officer										
Developer Head Office Site Agent										
Sito Adont		I								

#### **Plans**

Plan EDP 1 Tree Protection Plan

(edp2425\_d040b 09 June 2022 DJ/BW)

Plan EDP 2 Tree Retention and Removal Plan – Drainage Strategy

(edp2425\_d038a 10 November 2021 GY/BW)

