

Site Investigation Photograph 95
Date: 31/8/22
Direction Photograph Taken: n/a.
Description: WS221 1.20 - 2.00m, showing River Terrace Deposits.



Site Investigation Photograph 96
Date: 25/8/22
Direction Photograph Taken: n/a.
Description: WS222 1.20 - 2.00m, showing River Terrace Deposits.



Site Investigation Photograph 97
Date: 25/8/22
Direction Photograph Taken: n/a.
Description: WS222 2.00 - 2.60m, showing River Terrace Deposits.



Site Investigation Photograph 98
Date: 31/8/22
Direction Photograph Taken: n/a.
Description: WS225 1.20 - 2.00m, showing River Terrace Deposits.



Site Investigation Photograph 99
Date: 23/8/22
Direction Photograph Taken: n/a.
Description: WS227 1.20 - 2.00m, showing River Terrace Deposits.



Site Investigation Photograph 100
Date: 23/8/22
Direction Photograph Taken: n/a.
Description: WS227 2.00 - 2.70m, showing River Terrace Deposits.



Site Investigation Photograph 101

Date: 5/9/22

Direction Photograph Taken: n/a.

Description: WS228 0.00 - 1.20m, showing Topsoil over River Terrace Deposits.



Site Investigation Photograph 102

Date: 2/9/22

Direction Photograph Taken: n/a.

Description: WS229 1.20 - 2.00m, showing River Terrace Deposits.



<p>Site Investigation Photograph 103</p>
<p>Date: 31/8/22</p>
<p>Direction Photograph Taken: n/a.</p>
<p>Description: WS231 1.20 - 5.00m, showing Head Deposits over River Terrace Deposits.</p>



<p>Site Investigation Photograph 104</p>
<p>Date: 5/9/22</p>
<p>Direction Photograph Taken: n/a.</p>
<p>Description: WS236 1.20 - 2.00m, showing River Terrace Deposits.</p>



<p>Site Investigation Photograph 105</p>	
<p>Date: 31/8/22</p>	
<p>Direction Photograph Taken: n/a.</p>	
<p>Description: WS238 1.20 - 5.00m, showing River Terrace Deposits over Oxford Clay Formation.</p>	

<p>Site Investigation Photograph 106</p>	
<p>Date: 1/9/22</p>	
<p>Direction Photograph Taken: n/a.</p>	
<p>Description: WS241 1.20 - 5.00m, showing Alluvium River Terrace Deposits over Oxford Clay Formation.</p>	

Site Investigation Photograph 107

Date: 5/9/22

Direction Photograph Taken: n/a.

Description: WS242
1.20 - 2.00m, showing River Terrace Deposits.



Site Investigation Photograph 108

Date: 2/9/22

Direction Photograph Taken: n/a.

Description: WS245
1.20 - 3.00m, showing Alluvium over River Terrace Deposits.



<p>Site Investigation Photograph 109</p>	
<p>Date: 2/9/22</p>	
<p>Direction Photograph Taken: n/a.</p>	
<p>Description: WS246 1.20 - 5.00m, showing Alluvium over River Terrace Deposits over Oxford Clay Formation.</p>	

<p>Site Investigation Photograph 110</p>	
<p>Date: 1/9/22</p>	
<p>Direction Photograph Taken: n/a.</p>	
<p>Description: WS251 1.20 - 5.00m, showing River Terrace Deposits over Oxford Clay Formation.</p>	

**Site Investigation
Photograph 111**

Date: 07/02/23

**Description: RO301
showing Alluvium
over first River
Terrace Deposits.**



**Site Investigation
Photograph 112**

Date: 08/02/23

**Description: RO301
showing Kellaways
Clay over the
Cornbrash
Formation.**



Site Investigation Photograph 113

Date: 08/02/23

Description: RO301, Cornbrash Formation over Forest Marble Formation.



Site Investigation Photograph 114

Date: 09/02/23

Description: RO301, Forest Marble Formation.



**Site Investigation
Photograph 115**

Date: 09/02/23

Description: RO301,
Forest Marble
Formation.



**Site Investigation
Photograph 116**

Date: 09/02/23

Description: RO301,
Forest Marble
Formation.



Site Investigation Photograph 117

Date: 09/02/23

Description: R0301, Forest Marble Formation.



Site Investigation Photograph 118

Date:

Description: R0301, Forest Marble Formation.



Site Investigation Photograph 119

Date: 09/02/23

Description: R0301 showing White Limestone Formation.



Site Investigation Photograph 120

Date: 09/02/23

Description: R0301 showing White Limestone Formation.



Site Investigation Photograph 121

Date: 03/02/23

Description: R0302 showing First River Terrace Deposits.



Site Investigation Photograph 122

Date: 03/02/23

Description: R0302 showing First River Terrace Deposits over Kellaways Clay.



Site Investigation Photograph 123

Date: 03/02/23

Description: R0302 showing the Cornbrash Formation.



Site Investigation Photograph 124

Date: 03/02/23

Description: R0302 showing Cornbrash Formation over the Forest Marble Formation.



Site Investigation Photograph 125

Date: 03/02/23

Description: R0302 showing Forest Marble Formation.



Site Investigation Photograph 126

Date: 06/02/23

Description: R0302 showing Forest Marble Formation.



Site Investigation Photograph 127

Date: 06/02/23

Description: R0302 showing Forest Marble Formation.



Site Investigation Photograph 128

Date: 06/02/23

Description: R0302 showing Forest Marble Formation.



Site Investigation Photograph 129

Date: 06/02/23

Description: R0302 showing Forest Marble Formation over White Limestone Formation.



Site Investigation Photograph 130

Date: 06/02/23

Description: R0302 showing White Limestone Formation.



Site Investigation Photograph 131

Date: 24/01/23

Description: R0303 showing, Alluvium over First River Terrace Deposits.



Site Investigation Photograph 132

Date: 24/01/22

Description: R0303 showing, First River Terrace Deposits over Kellaways Clay.



Site Investigation Photograph 133

Date: 24/01/23

Description: R0303 showing, Cornbrash Formation.



Site Investigation Photograph 134

Date: 24/01/23

Description: R0303 showing Cornbrash Formation.



Site Investigation Photograph 135

Date: 24/01/23

Description: R0303 showing Cornbrash Formation.



Site Investigation Photograph 136

Date: 24/01/23

Description: R0303 showing Cornbrash Formation.



Site Investigation Photograph 137

Date: 24/01/23

Description: R0303 showing Cornbrash Formation over Forest Marble Formation.



Site Investigation Photograph 140

Date: 25/01/23

Description: R0303 showing Cornbrash Formation.



Site Investigation Photograph 141

Date: 25/01/23

Description: R0303 showing Cornbrash Formation.



Site Investigation Photograph 30

Date: 25/01/23

Description: R0303 showing Cornbrash Formation.



Site Investigation Photograph 31

Date: 25/01/23

Description: R0303 showing Cornbrash Formation over White Limestone Formation



Site Investigation Photograph 32

Date: 25/01/23

Description: R0303 showing White Limestone Formation.



Site Investigation Photograph 33

Date: 25/01/23

Description: R0303 showing White Limestone Formation.



Site Investigation Photograph 34

Date: 26/01/23

Description: R0304 showing, Alluvium over Kellaways Clay Member.



Site Investigation Photograph 35

Date: 27/01/23

Description: R0304 showing Kellaways Clay Member over Cornbrash Limestone Formation.



Site Investigation Photograph 36

Date: 27/01/23

Description: R0304 showing Cornbrash Limestone Formation.



Site Investigation Photograph 37

Date: 27/01/23

Description: R0304 showing Cornbrash Limestone Formation over Forest Marble Formation.



Site Investigation Photograph 38

Date: 27/01/23

Description: R0304 showing Forest Marble Formation.



Site Investigation Photograph 142

Date: 27/01/23

Description: R0304 showing Forest Marble Formation.



Site Investigation Photograph 143

Date: 27/01/23

Description: R0304 showing Forest Marble Formation.



<p>Site Investigation Photograph 41</p>
<p>Date: 31/01/23</p>
<p>Description: R0304 showing Forest Marble Formation.</p>



<p>Site Investigation Photograph 42</p>
<p>Date: 31/01/23</p>
<p>Description: R0304 showing Forest Marble Formation.</p>



<p>Site Investigation Photograph 43</p>
<p>Date: 31/01/23</p>
<p>Description: R0304 showing Forest Marble Formation over the White Limestone Formation.</p>



<p>Site Investigation Photograph 44</p>
<p>Date: 31/01/23</p>
<p>Description: R0304 showing White Limestone Formation.</p>



Site Investigation Photograph 45

Date: 31/01/23

Description: R0305 showing River Terrace Deposits over the Oxford Clay Formation.



Site Investigation Photograph 46

Date: 01/02/23

Description: R0305 showing the Oxford Clay Formation.



Site Investigation Photograph 47

Date: 01/02/23

Description: R0305 showing the Oxford Clay Formation.



Site Investigation Photograph 48

Date: 01/02/23

Description: R0305 showing the Oxford Clay Formation.



Site Investigation Photograph 49

Date: 01/02/23

Description: R0305 showing the Oxford Clay Formation.



Site Investigation Photograph 50

Date: 01/02/23

Description: R0305 showing the Oxford Clay Formation.



Site Investigation Photograph 51

Date: 01/02/23

Description: R0305 showing the Oxford Clay Formation.



Site Investigation Photograph 52

Date: 01/02/23

Description: R0305 showing the Kellaways Sand Member.



Site Investigation Photograph 53

Date: 02/02/23

Description: RO305 showing the Kellaways Clay Member.



Site Investigation Photograph 54

Date: 02/02/23

Description: RO305 showing the Kellaways Clay Member over the Cornbrash Limestone Formation.



Site Investigation Photograph 55

Date: 02/02/23

Description: R0305 showing the Cornbrash Limestone Formation.



Site Investigation Photograph 56

Date: 07/02/23

Description: R0306 showing the Alluvium.



Site Investigation Photograph 57

Date: 07/02/23

Description: R0306 showing the Alluvium over the Cornbrash Limestone Formation.



Site Investigation Photograph 58

Date: 07/02/23

Description: R0306 showing the Cornbrash Limestone Formation over the Forest Marble Formation.



Site Investigation Photograph 59

Date: 08/02/23

Description: R0307 showing the River Terrace Deposits.



Site Investigation Photograph 60

Date: 08/02/23

Description: R0307 showing the River Terrace Deposits over the Cornbrash Limestone Formation.



Site Investigation Photograph 61

Date: 08/02/23

Description: R0307 showing the Cornbrash Limestone Formation.



Site Investigation Photograph 62

Date: 08/02/23

Description: R0307 showing the Cornbrash Limestone Formation over the Forest Marble Formation.



Site Investigation Photograph 63

Date: 06/02/23

Description: R0308 showing the River Terrace Deposits.



Site Investigation Photograph 64

Date: 06/02/23

Description: R0308 showing the River Terrace Deposits.



Site Investigation Photograph 65

Date: 06/02/23

Description: R0308 showing the River Terrace Deposits over the Kellaways Clay Member over the Cornbrash Limestone Formation.



Site Investigation Photograph 66

Date: 06/02/23

Description: R0308 showing the Cornbrash Limestone Formation.



Site Investigation Photograph 65

Date: 07/02/23

Description: R0308 showing the Forest Marble Formation.



Site Investigation Photograph 66

Date: 07/02/23

Description: R0308 showing the Forest Marble Formation.



<p>Site Investigation Photograph 67</p>
<p>Date: 09/02/23</p>
<p>Description: R0309 showing the River Terrace Deposits.</p>



<p>Site Investigation Photograph 68</p>
<p>Date: 09/02/23</p>
<p>Description: R0309 showing the Cornbrash Limestone Formation.</p>



Site Investigation Photograph 69

Date: 09/02/23

Description: R0309 showing the Forest Marble Formation.



Site Investigation Photograph 70

Date: 01/02/23

Description: R0310 showing the River Terrace Deposits over Kellaways Clay Member.



Site Investigation Photograph 71

Date: 13/02/23

Description: R0310 showing the Kellaways Clay Member over the Cornbrash Limestone Formation.



Site Investigation Photograph 72

Date: 13/02/23

Description: R0310 showing the Cornbrash Limestone Formation.



Site Investigation Photograph 73

Date: 13/02/23

Description: R0310 showing the Cornbrash Limestone Formation over the Forest Marble Formation.



Site Investigation Photograph 74

Date: 10/02/23

Description: R0311 showing the River Terrace Deposits.



Site Investigation Photograph 75

Date: 10/02/23

Description: R0311 showing the River Terrace Deposits over the Cornbrash Limestone Formation.



Site Investigation Photograph 76

Date: 10/02/23

Description: R0311 showing the Cornbrash Limestone Formation.



Site Investigation Photograph 78

Date: 10/02/23

Description: R0311 showing the Cornbrash Limestone Formation over the Forest Marble Formation.



Site Investigation Photograph 79

Date: 09/02/23

Description: R0312 showing the River Terrace Deposits over the Kellaways Sand Formation.



Site Investigation Photograph 80

Date: 09/02/23

Description: R0312 showing the Kellaways Sand Member over the Kellaways Clay Member.



Site Investigation Photograph 81

Date: 09/02/23

Description: R0312 showing the Kellaways Sand Member over the Kellaways Clay Member



Site Investigation Photograph 82

Date: 09/02/23

Description: R0312 showing the Cornbrash Limestone Formation.



Site Investigation Photograph 83

Date: 09/02/23

Description: R0312 showing the Cornbrash Limestone Formation over the Forest Marble Formation.



Site Investigation Photograph 84

Date: 09/02/23

Description: R0313 showing the River Terrace Deposits over the Cornbrash Limestone Formation.



Site Investigation Photograph 85

Date: 09/02/23

Description: R0313 showing the River Terrace Deposits over the Cornbrash Limestone Formation.



Site Investigation Photograph 86

Date: 09/02/23

Description: R0313 showing the Cornbrash Limestone Formation over the Forest Marble Formation.



Site Investigation Photograph 87

Date: 09/02/23

Description: R0314 showing the Alluvium over the River Terrace Deposits.



Site Investigation Photograph 88

Date: 09/02/23

Description: R0314 showing the River Terrace Deposits over the Cornbrash Limestone Formation over the Forest Marble Formation.



Site Investigation Photograph 89

Date: 09/02/23

Description: R0314 showing the Cornbrash Limestone Formation over the Forest Marble Formation.



Site Investigation Photograph 90

Date: 10/02/23

Description: R0315 showing the Alluvium.



Site Investigation Photograph 91

Date: 10/02/23

Description: R0315 showing the River Terrace Deposits over the Cornbrash Limestone Formation.



Site Investigation Photograph 92

Date: 13/02/23

Description: R0316 showing the Alluvium.



Site Investigation Photograph 93

Date: 13/02/23

Description: R0316 showing the Kellaways Clay Member over the Cornbrash Limestone Formation.



Site Investigation Photograph 94

Date: 13/02/23

Description: R0316 showing the Cornbrash Limestone Formation.



Site Investigation Photograph 95

Date: 13/02/23

Description: R0316 showing the Cornbrash Limestone Formation over the Forest Marble Formation.



Site Investigation Photograph 96

Date: 02/02/23

Description: R0317 showing the Alluvium over the River Terrace Deposits.



Site Investigation Photograph 97

Date: 02/02/23

Description: R0317 showing the River Terrace Deposits over the Forest Marble Formation.



Site Investigation Photograph 98

Date: 02/02/23

Description: R0317 showing the Forest Marble Formation.



Site Investigation Photograph 99

Date: 02/02/23

Description: R0317 showing the Forest Marble Formation.



Site Investigation Photograph 100

Date: 02/02/23

Description: R0317 showing the Forest Marble Formation.



Site Investigation Photograph 101

Date: 02/02/23

Description: R0317 showing the Forest Marble Formation.



Site Investigation Photograph 102

Date: 02/02/23

Description: R0317 showing the Forest Marble Formation.



Site Investigation Photograph 103

Date: 06/02/23

Description: R0318 showing the Alluvium over the River Terrace Deposits.



Site Investigation Photograph 104

Date: 06/02/23

Description: R0318 showing the River Terrace Deposits.



Site Investigation Photograph 105

Date: 06/02/23

Description: R0318 showing the River Terrace Deposits.

