

APPENDIX 11.1: ARACHAEOLOGY AND CULTURAL HERITAGE GAZETTEER

APPENDIX 11.1 (A) : BUILT HERITAGE GAZETTEER: STRUCTURES WITHIN THE SITE

Explanation of References used within this Gazetteer:

A5

ACTA, Oxford Archaeology and The Tourism Company *Former RAF Upper Heyford Conservation Plan* (2005)
(3) Volume 3: Gazetteer and Appendices
(Oax) OA reference number within Gazetteer

ACTA 2005

ACTA *Former RAF Upper Heyford Airbase: Landscape South of the Cold War Zone* (2006)
The number following the reference indicates the Character Area within the 2006 report, which has been changed for the purposes of this Assessment (i.e - 4C).

RE6

Roger Evans Associates Ltd. *Heyford Park Building Appraisal* (2006)
The number followed by a hash and a further number refers to the area and building number within this report (i.e 9/234 is Area 9, building 234)

NOC

Documents held by NOC within Heyford Park House

u/d

Undetermined

OA Ref.	Scheduled/ Listed	Building Number	Function	Date	Building Description	Reference
OA1 CHARACTER AREA 1: SPORTS FIELDS AND LARGE BUILDINGS						
OA1A Character Area 1: Sports Fields						
OA1A.1		583	Gymnasium	1976	Pebble dash concrete walls with flat roof.	ACTA 2006 2A. p. 13. RE6 3/583
		515	Former leisure	1983	Timber frame with walls removed. Tiled roof.	ACTA 2006 2A. p. 13. RE6 3/515
		527	Electrical sub station	1976	Timber panels with concrete posts.	ACTA 2006 2A. p. 13. RE6 3/527
		528	Store	1982	Pebbled dashed walls and corrugated roof.	ACTA 2006 2A. p. 13. RE6 3/528
		570	Former store	u/d	Blockwork walls and metal monopitch roof.	ACTA 2006 2A. p. 13. RE6 3/570
		567, 577, 595, 599	Baseball dugouts	1977, 1982, 1977, 1980	Blockwork walls with monopitch roof.	ACTA 2006 2A. p. 13. RE6 3/567, 577, 595, 599.
		578	Fuel inlet	1955	Brick with concrete roof	ACTA 2006 2A. p. 13. RE6 3/578. NOC.
		584	Store	1982	Pebble dash concrete walls with flat roof.	ACTA 2006 2A. p. 13. RE6 3/584
		590, 597	Waste disposal pit	1940	Pit surrounded by 1.8m high fence.	ACTA 2006 2A. p. 13. RE6 3/590, 597
		UH3	Sub station	u/d	Timber panel fencing supported by concrete posts.	ACTA 2006 2A. p. 13. RE6 3/UH3
		UH5	Former viewing tower	u/d	Blockwork walls with asphalt roof.	ACTA 2006 2A. p. 13. RE6 3/UH5
		592	Tennis courts	1980	Asphalt	ACTA 2006 2A. p. 13. NOC
		UH15	Office	u/d	Blockwork walls with metal pitched roof.	ACTA 2006 2B. p.14. RE6 3/UH15
		579	B house	1980	Steel frame, metal cladding to walls	ACTA 2006 2B. p.14
OA 1B Character Area 1B: Superstore/ Hospital						
OA1B.1		581	Former supermarket	1975	Blockwork walls with flat roof.	ACTA 2006 2B. p.14. RE6 3/581
OA1B.2		582	Former hospital -60 bed	1982	Pebble dash panel walls with flat roof.	ACTA 2006 2B. p.14. RE6 3/582
		566	Former store	1989	Blockwork walls with metal monopitch roof.	ACTA 2006 2B. p.14. RE6 3/566
OA2 CHARACTER AREA 2: SOUTH RESIDENTIAL BUILDINGS						
OA2A Character Area 2A: South Bungalows						
		640, 649, 677, 733, 742,	Semi-detached single story housing	1957	Concrete panel walls with tiled roof.	ACTA 2006 3A. p.14. RE6 2/640, 649, 677, 733, 742
		642, 644, 655,656, 657, 659, 661, 663, 664, 670, 671, 674, 675, 682, 684, 868, 688, 692, 700, 701,710, 712, 714, 718,	Semi-detached single story housing	1957	Concrete panel wall construction with tiled roof.	ACTA 2006 3A. p.14. RE6 2/642, 644, 655,656, 657, 659, 661, 663, 664, 670, 671, 674, 675, 682, 684, 868, 688, 692, 700, 701,710, 712, 714, 718, 730, 731, 732, 735, 740,

		730, 731, 732, 735, 740, 744, 750, 751, 752, 753, 754, 755, 756, 757, 759, 765, 767, 768, 769, 770, 771				744, 750, 751, 752, 753, 754, 755, 756, 757, 759, 765, 767, 768, 769, 770, 771
		646, 648, 650, 651, 652, 653, 662, 665, 666, 667, 668, 669, 681, 683, 685, 687, 690, 691, 702, 703, 704, 705, 706, 707, 709, 711, 713, 715, 716, 717, 720, 721, 722, 723, 724, 725, 726, 728, 736, 745, 746, 747, 760, 761, 762, 763, 764, 766, 772, 773, 774, 775, 776, 778, 780	Semi-detached single story housing	1957	Concrete panel wall construction with tiled roof.	ACTA 2006 3A. p.14. RE6 2/646, 648, 650, 651, 652, 653, 662, 665, 666, 667, 668, 669, 681, 683, 685, 687, 690, 691, 702, 703, 704, 705, 706, 707, 709, 711, 713, 715, 716, 717, 720, 721, 722, 723, 724, 725, 726, 728, 736, 745, 746, 747, 760, 761, 762, 763, 764, 766, 772, 773, 774, 775, 776, 778, 780
		673, 738	Electric sub-station	1950	Enclosure constructed from timber fence panels.	ACTA 2006 3A. p.14. RE6 2/673, 738
		779	Sewage pump	1989	Rendered brick with timber, tiled roof.	ACTA 2006 3A. p.14. RE6 2/779
OA2B Character Area 2B: Mixed Use Area						
OA2B.1		572	Chapel	1961	Beige brindled brick walls with flat asphalt roof.	ACTA 2006 3B. p.15. RE6 2/572
OA2B.2		549	Community centre (ancillary building)	1945	Steel frame with brick piers and pebble dash. Metal clad roof and gable ends.	ACTA 2006 3B. p.15. RE6 2/549
OA2B.3		543, 544	Housing (Warrant Officers)	1925	Brick walls, and tiled roof.	ACTA 2006 3B. p.15. RE6 2/543, 544
OA2B.4		547	Former launderette/store	1935	Red brick with timber/tiled pitched roof	ACTA 2006 3B. p.15. RE6 2/547
OA2B.5		546	Former credit union	1977	Blockwork walls with asphalt roof.	ACTA 2006 3B. p.15. RE6 2/546
		291	Water tower	1972	Metal frame supporting metal tank	ACTA 2006 3B. p.15. RE6 2/291
		542, 548	Electric sub station	1940	Enclosure of timber fence panels	ACTA 2006 3B. p.15. RE6 2/542, 548
		546X	Housing	1930	Red brick walls with pitched, tiled roof	ACTA 2006 3B. p.15. RE6 2/546X
		551	Water pump	1935	Brick construction with flat asphalt roof	ACTA 2006 3B. p.15. RE6 2/551
		552	Water tanks (2 no.)	1952	Metal containers with brick plinth	ACTA 2006 3B. p.15. RE6 2/552
		565, 573	Water tank	1979, 1987	Poured concrete construction with concrete panels.	ACTA 2006 3B. p.15. RE6 2/565, 573
		568	Former waste disposal	1945	Poured concrete pits.	ACTA 2006 3B. p.15. RE6 2/568
		588	Store	1975	Concrete blockwork walls with asbestos roof.	ACTA 2006 3B. p.15. RE6 2/588.
		UH2	Sub-stations	u/d	2 structures with brick walls and asphalt roof.	ACTA 2006 3B. p.15. RE6 2/UH2
OA 2C Character Area 2C: Semi-Detached Houses						
		553-562	Semi-detached housing	1953	Brown brindled brick with timber, tiled pitched roof.	ACTA 2006 3B. p.15. RE6 2/553-562

OA2D Character Area 2D: Carswell Circle North						
		535- 540	Terraced housing (Married Airmen)	1925	Terraced units of rendered brick and tiled roof.	ACTA 2006 3D. p.15. RE6 2/535-540
OA2E Character Area 2E: Carswell Circle South						
		530, 531, 533, 534	Terraced housing	1925	Terraced red brick housing with tiled roofs	ACTA 2006 3E. p.16. RE6 2/530, 531, 533, 534
		532	Electric sub-station	1949	Part brick, part timber enclosure.	ACTA 2006 3E. p.16. RE6 2/532
OA3 CHARACTER AREA 3: BARRACKS AND INSTITUTIONS						
OA3A Character Area 3A Store/ Petrol Station						
OA3A.1		459	Single Sergeants Quarters	1925	Red bricked with tiled roof.	ACTA 2006 4B. p.17. RE6 1/459.
OA3A.2		492	Store	1985	Brown brick walls and flat metal roof.	ACTA 2006 4B. p.17. RE6 1/492
OA3A.3		493	Former petrol station	1985	Metal canopy and brick booth	ACTA 2006 4B. p.17. RE6 1/493
		460	Bus shelter	1939	Brick with tiled roof	ACTA 2006 4B. p.17
OA3B Character Area 3B: Parade Ground Buildings						
OA3B.1		457	Sergeants' Mess	1925	Red bricked with tiled roof	ACTA 2006 4B. p.17. RE6 1/457
OA3B.2		455	The Institute	1925	Red bricked with tiled roof.	ACTA 2006 4B. p.17. RE6 1/455.
OA3B.3		474	Dining room and Cookhouse	1925	Red brick walls with tiled roof.	ACTA 2006 4B. p.17. RE6 1/474
OA3B.4		475	Ration store and shop	1925	Red brick walls with tiled roof.	ACTA 2006 4B. p.17. RE6 1/475
OA3B.5		450, 466, 471, 480, 483, 440	Barracks Blocks (Barrack block type C)	1925	Red bricked buildings with concrete floors and tiled roof.	ACTA 2006 4B. p.17. RE6 1/466,471,480, 483
OA3B.6		485	Type B barrack block	1925	Red brick walls with tiled roof.	ACTA 2006 4B. p.17. RE6 1/485
OA3B.7		467	Boiler house (Central Heating Station)	1925	Red brick with concrete roof.	ACTA 2006 4B. p.17. RE6 1/467.
OA3B.8		472A	Mess Complex	1939	Concrete block walls with metal doors and windows, and a flat roof.	ACTA 2006 4B. p.17. RE6 1/472A
		440b	Boiler room	u/d	Brick on concrete plinth with flat roof	ACTA 2006 4B. p.17
		442	Child care centre	1984	Red brick walls with timber and tiled roof	ACTA 2006 4B. p.17
		449, 484, 485, 470	Disused building	1940/1977	Metal clad walls over timber construction.	ACTA 2006 4B. p.17. RE6 1/449, 484
		454	Water tank	1950	Timber fence enclosure	ACTA 2006 4B. p.17. RE6 1/454
		486	Offices	1976	Timber prefabricated unit with flat asphalt roof.	ACTA 2006 4B. p.17. RE6 1/486
		461	Pre-fabricated cabin and metal sheds	1939	Prefabricated cabin and metal sheds.	ACTA 2006 4B. p.17. RE6 1/461.
		468	Office/store	1940	Prefabricated unit with metal clad walls and metal roof.	ACTA 2006 4B. p.17. RE6 1/468.
		472B	Recreation centre	1939	Concrete plinth with panel cladding to walls.	ACTA 2006 4B. p.17. RE6 1/472B
		476	Electric sub-station	1950	Red bricked enclosure	ACTA 2006 4B. p.17. RE6 1/476

		481	Thrift shop	1973	Timber cladding panels to walls. Flat roof.	ACTA 2006 4B. p.17. RE6 1/481
		529	Former Leisure unit	1935	Metal clad walls, flat concrete roof.	ACTA 2006 4B. p.17. RE6 1/529
		UH8	u/d	u/d	Mixed brick construction with flat roof.	ACTA 2006 4B. p.17. RE6 1/UH8
		UH11	Portakabin		Portakabin	ACTA 2006 4B. p.17. RE6 1/UH11
OA3C Character Area 3C: West Barracks						
		445, 593, 594, 596, 598	Barracks blocks	1970, 1972	Red brick and blockwork walls with flat roof.	ACTA 2006 4C. p.17. RE6 1/445,446, 593, 594, 596, 598
		441	Boiler house	1970	Brown brick walls, partially metal clad	ACTA 2006 4C. p.17. RE6 1/441
		500	Barracks blocks (Type H Barrack)	1926	Barrack accommodation, brick walls. Tiled roof.	ACTA 2006 4C. p.17. NOC
		502	Offices	1939	Building clad in clay-chip rendered panels, concrete tiles on roof.	ACTA 2006 4C. p.17. RE6 1/502
		UH10	Sub-station	u/d	Timber fence panels supported by concrete posts.	ACTA 2006 4C. p.17. RE6 1/UH10
OA3D Character Area 3D: 1930s Area						
OA3D.1		488	The Institute -Lamplighter Inn/Dining facility	1935	Red brick walls with flat concrete roof.	ACTA 2006 4D. p.18. RE6 1/488
OA3D.2		489, 498 & 500	Barracks blocks (Type H Barrack)	1926	Red bricked building with tiled roof.	ACTA 2006 4D. p.18. RE6 1/489, 498.
		443	Store	1971	Brown brick building with flat roof	ACTA 2006 4D. p.18. RE6 1/443
		444	Building	1982	Prefabricated timber unit	ACTA 2006 4D. p.18. RE6 1/444
		487	Electric sub-station	1940	Enclosure with metal fence	ACTA 2006 4D. p.18. RE6 1/487
		446	Barracks block	1970, 1972	Red brick and blockwork walls with flat roof.	ACTA 2006 4C. p.17. RE6 1/446
		491	Store	1935	Brown brick walls with timber gables and timber pitched roof	ACTA 2006 4D. p.18. RE6 1/491
		UH9	Generator		Brick walls with flat roof.	ACTA 2006 4D. p.18. RE6 1/UH9
OA4 Character Area 4: Eastern Huts						
		400-405, 407-409	Office	1939	Prefabricated units/Part brick walls with corrugated roof	ACTA 2006 5. p.18. RE6 1/400-405,407-409
		406	Incinerator	1982	Concrete slab, high brick wall enclosure	ACTA 2006 5. p.18
		410	Boiler house	1939	Brick walls with sheet metal roof	ACTA 2006 5. p.18. RE6 1/410
		425	Electrical sub-station	1952	Brick walls with metal vents	ACTA 2006 5. p.18 RE6 1/425
		UH12	Tank	u/d	Metal tank surrounded by timber boards and chicken wire	ACTA 2006 5. p.18. RE6 1/UH12
		UH13	Office	u/d	Corrugated metal clad walls with pitched metal roof.	ACTA 2006 5. p.18. RE6 1/UH13

OA5 CHARACTER AREA 5: TECHNICAL AREA						
OA5A Character Area 5A Aircraft Sheds						
OA5A.1		172, 345, 350, 151, 315, 320	Type A Aircraft sheds	1925	Steel frame, concrete infill, asbestos multipitched roof.	ACTA 2006 6A,6B. p.19. RE6, 7/172, 345, 350
OA5A.2		130	Main Workshope	1940	Brickwork with pitched metal roofs	ACTA 2006 6A,6B. p.19. RE6, 7/130
OA5A.3		158	Night Flying Equipment Store	1935	Painted brick walls with parapet to flatroof.	ACTA 2006 6A,6B. p.19. RE6, 7/158
OA5A.4	Scheduled Monu- ment (30906-05)	126	Battle Command Centre	1980	Hardened concrete, single storey with a flat roof and blast walls. Designed to be self sufficient and contains a generating plant and air filters	A5 (3) OA7. ACTA 2006 6A,6B. p.19. RE6, 7/126. NOC
		171, 316	Petrol Tanker Sheds	1935, 1948	Brick walls with parapet to flat roof	ACTA 2006 6A,6B. p.19. RE6, 7/171, 316
		89B	Blast separation wall	1939	Brick wall with concrete buttresses	RE6, 6/89B. NOC
		89C	Containers (2 no)	1939	Metal transport containers	RE6, 6/89C. NOC
		89	u/d	1939	Brick structure	RE6, 6/89
		81	u/d	1940	Concrete structure	RE6, 6/81
		318	Office	1950s	Rendered walls with flat roof/ metal clad industrial shed	ACTA 2006 6A,6B. p.19. RE6, 7/123, 318
		156	Store	1940, 1935	Rendered walls with flat roof.	ACTA 2006 6A,6B. p.19. RE6, 7/156
		131	Boiler house	1965	Brick walls with flat asphalt roof	ACTA 2006 6A,6B. p.19. RE6, 7/131
		157	Community - scouts building (Engine Test House)	1935	Brick walls with pitched metal roof	ACTA 2006 6A,6B. p.19. RE6, 7/157
		1483	Store	u/d	Metal cladding to walls, metal roof	ACTA 2006 6A,6B. p.19. RE6, 7/1483
		UH40, 170, 312	Electric sub-station	1940	Painted brick walls with metal gate at entry/fenced enclosure	ACTA 2006 6A,6B. p.19. RE6, 7/UH40, 170, 312
		313	Pavillion	1950	Steel frame with metal cladding and metal pitched roof	ACTA 2006 6A,6B. p.19. RE6, 7/313
		317	Workshop	1950	Rendered walls with pitched corrugated asbestos roof	ACTA 2006 6A,6B. p.19. RE6, 7/317
		317a	Canopy	1950	Remains of brick chimney, covered by metal canopy on metal posts	ACTA 2006 6A,6B. p.19. RE6, 7/317a. NOC
		339	Com air plant	1982	Brick walls containing vents. Flat asphalt doors and timber double doors.	ACTA 2006 6A,6B. p.19. RE6, 7/339
		346	Fuel tanks		Brick walls with shallow metal mono-pitch roof. Fuel tanks adjacent.	ACTA 2006 6A,6B. p.19. RE6, 7/346
		349	Gate house	1990	Brick walls with pitched, tiled roof supported by timber posts.	ACTA 2006 6A,6B. p.19. RE6, 7/349

		350A	2 Portakabins	1925	2 portakabins	ACTA 2006 6A,6B. RE6, 7/350A. NOC
		UH37, UH38	Flowerbed	u/d	Brick wall	ACTA 2006 6A,6B. p.19. RE6, 7/UH37, 38
		UH41	u/d	u/d	u/d	
OA5B Character Area 5B Service Area						
OA5B.1		125	Station Armoury and lecture room (QEK office)	1926	Brown/ red brindled brick walls with pitched, tiled hipped roof.	ACTA 2006 6A,6B. p.19. RE6, 7/125
OA5B.2	Scheduled Monument (no. 30906-05)	129	Hardened Telephone Exchange	1987	Single storey with a taller section which house blast proof roof vents. Retains dull brown 'Novolant' finish	A5 (3) OA8. ACTA 2006 6A,6B. p.19. RE6, 7/129
OA5B.3		115, 117	Motor Transport Sheds	1939	Concrete and steel structure with brick and stone infill	ACTA 2006 6B. p. 19. RE6, 7/115,117
OA5B.4		133	Main Church and Store (Junior Citizens and Thames Valley Medical Rescue)	1926	Brick walls with pitched, tiled roof	ACTA 2006 6B. p. 19. RE6, 7/133
OA5B.5		59	Works Service Building	1940	Painted brickwork with asbestos tiles on pitched roof.	ACTA 2006 6E. p.20. RE6 6/59
OA5B.6		103	Workshop	1940	Brick walls with pitched tiled roof.	ACTA 2006 6B. p. 19
OA5B.7		114	The Power House	1940	Brick walls with flat roof.	ACTA 2006 6B. p. 19. RE6, 7/114
		67	u/d	u/d	u/d	
		66, 68	Offices in use	1939	Brick building with metal pitched roof.	ACTA 2006 6E. p.20. RE6 6/66, 68
		72	Two storage sheds (Operations Blocks)	1940	Steel frame with timber panel and corrugated steel cladding	ACTA 2006 6E. p.20. RE6 6/72
		56	The Works Squadron	1951	Painted brickwork with metal pitched roof and windows.	ACTA 2006 6E. p.20. RE6 6/56
		53	Office	1940	Pebbled dashed prefabricated panel construction to walls. metal pitched roof.	ACTA 2006 6E. p.20. RE6 6/53
		54	Single story hut	1940	Rendered walls with corrugated roof.	ACTA 2006 6E. p.20. RE6 6/54
		70	Conference room	1972	Prefabricated unit, timber clad.	ACTA 2006 6E. p.20. RE6 6/70
		64, 65	Building	1940s	Brick walls, flat roof.	ACTA 2006 6E. p.20. RE6 6/64, 65, 73
		101, 102	The Fire Party House (Offices/Workshop)	1939	Brick and metal clad buildings.	ACTA 2006 6B. p. 19. RE6, 7/101,102
		62, 69	Workshops	1981	Blockwork walls and metal pitched roof.	ACTA 2006 6E. p.20. RE6 6/62,69
		106	Storage (Battle Command Centre)	1970s	Brick and metal clad walls with metal roof and metal windows.	ACTA 2006 6B. p. 19. RE6, 7/106
		UH 46	Office	u/d	Prefabricated unit	RE6, 6/UH46
		107	Water tank (Reservoir)	1952	Concrete	ACTA 2006 6B. p. 19. A6.(A.2)
		79	Garage	1940	Painted brick walls with parapet to flat roof.	ACTA 2006 6B,6C,6D. p.20. RE6 6/79

		108	Water tower (High level water tank)	1952	Concrete structure supporting concrete tank	ACTA 2006 6B. p. 19. A6.(A.2)
		113	Transformer enclosure	1920s	Red brick flat roof postwar additions	ACTA 2006 6B. p. 19. A6.(A.2)
		113b	Electric sub-station	u/d	Painted brick walls, flat roof.	ACTA 2006 6B. p. 19. RE6, 7/113b
		113a	Tanks	1990	Metal tanks on concrete plinth, with brick walled enclosure behind.	ACTA 2006 6B. p. 19. RE6 7/113a. NOC
		118	Office (Link trainer buildings)	1935	Brick walls with parapet to flat roof	ACTA 2006 6B. p. 19. RE6, 7/118
		119	Garage and store (The protected long bay)	1939	Brick walls with parapet to flat roof	ACTA 2006 6B. p. 19. RE6, 7/119
		145	Inflammables Store	1935	Brick walls with flat roof.	ACTA 2006 6B. p. 19. RE6, 7/145
		UH39	Tank	u/d	Brick plinth supporting metal tank	ACTA 2006 6A,6B. p.19. RE6, 7/UH39
		124	store	1940, 1935	Rendered walls with flat roof.	ACTA 2006 6A,6B. p.19. RE6, 7/156
		121	Water tank	1952	Timber panel fence enclosure	ACTA 2006 6A,6B. p.19. RE6, 7/121
		146	The Lubricant store	1926	Brick walls with pitched, tiled roof	ACTA 2006 6B. p. 19
		132	The Parachute store	1926	Brick walls with pitched, tiled roof	ACTA 2006 6B. p. 19. RE6, 7/132
		123	Office	1950s	Rendered walls with flat roof/ metal clad industrial shed	ACTA 2006 6A,6B. p.19. RE6, 7/123, 318
		147	Office (Link trainer building)	1935	Concrete single storey building with external piers.	ACTA 2006 6B. p. 19. RE6, 7/147
		148	The gas defence centre (Office)	u/d	Brick walls with parapet to flat roof, and metal windows	ACTA 2006 6B. p. 19. RE6, 7/148
		149	Fenced enclosure	1950	High timber panel fence	ACTA 2006 6B. p. 19. RE6, 7/149
OA5C Character Area 5C: Copse and Open Ground						
		80	Workshops, car wash	1953	Industrial shed type buildings, brick or metal clad.	ACTA 2006 6B,6C,6D. p.20. RE6 6/80. NOC
		84	Petrol Kiosk	1975	Concrete block	RE6, 6/84
		85	Store/workshop	1981	Small brick structure with timber door and metal roof	RE6, 6/85. NOC
		86	Type depot -QEK	1981	Brick building with metal roof.	RE6, 6/86
		88	Industrial shed - Ranik	1986	Metal clad shed	RE6, 6/88
		89A	Petrol pump booth	1939	Small brick structure with tiled roof	RE6, 6/89A. NOC
		UH44	Electric sub-station		Concrete plinth	RE6, 6/UH44
OA5D Character Area 5D: Post-War Open Landscape						
OA5D.1		77, 78	Innovation centre	1971	Brick walls with exposed concrete floor slabs. Tiled, pitched roof.	RE6 6/77, 78
OA5D.2		41	Former dormitory	1987	Red brick walls with pitched, tiled roof.	ACTA 2006 6D. p.20. RE6 6/41
OA5D.3		32-35	The Commissary (General Storage/Workshops)	1947	Steel frame, metal clad, pitched metal roof industrial sheds	ACTA 2006 6D. p.20. RE6 6/32-34
		2x, 3x, 4x	Metal shed	u/d	Metal shed with flat metal roof.	ACTA 2006 6D. p.20. RE6 6/2x, 3x,

						4x
		75	Water store	1950	High timber fence enclosing pond	ACTA 2006 6E. p.20. RE6 6/75
		36	Office	1970	Brown brick walls with flat asphalt roof	ACTA 2006 6D. p.20. RE6 6/36
		38	Carwash	1986	Concrete	ACTA 2006 6D. p.20. RE6 6/38
OA4E Character Area 4E: 1920s Core						
OA5E.1		51	The Briefing Rooms (Former Office/Admin)	1942	Brick plinth, timber weather boarding, metal clad pitched roof	ACTA 2006 6E. p.20. RE6 6/51
OA5E.2		52	Station Offices (Heyford House - Office/Admin)	1935	Brindled brick with black mortar. Tiled pitched roof.	ACTA 2006 6E. p.20. RE6 6/52
OA5E.3		100	The Guardhouse (Thames Valley Police)	1925	Brick with pitched, tiled roof.	ACTA 2006 6B. p. 19. RE6, 7/100
OA5E.4		74	Officers' Mess and Single Officers' Quarters	1925	Red brick with steep pitched tiled roof.	ACTA 2006 6E. p.20. RE6 6/74
		63	Water tank	1952	Metal structure supporting metal tank	ACTA 2006 6E. p.20. RE6 6/63
		73	Squash Racquets Court	u/d	Brick walls with metal pitched roof	ACTA 2006 6E. p.20. RE6 6/73
		104	Gatehouse	1990	Brick walls with pitched, tiled roof and timber windows	ACTA 2006 6B. p. 19. RE6, 7/104
OA6 CHARACTER AREA 6: NORTH RESIDENTIAL AREA						
OA6A Character Area 6A: Officer Housing						
OA6A.1		1, 3, 5,	4 Bed semi detached houses	1947	Brick walls with pitched, tiled roofs	ACTA 2006 7A. p.21. RE6 5/1,3,5
OA6A.1		2, 4,	5 Bed detached houses	1947	Brick walls with pitched, tiled roofs	ACTA 2006 7A. p.21. RE6 5/2,4
OA6A.1		6, 7,	3 Bed detached houses	1947	Brick walls with pitched, tiled roofs	ACTA 2006 7A. p.21. RE6 5/6,7
OA6A.1		8, 9,	4 Bed detached houses	1947	Brick walls with pitched, tiled roofs	ACTA 2006 7A. p.21. RE6 5/8,9
OA6A.1		10,11	3 Bed semi detached houses	1947	Brick walls with pitched, tiled roofs	ACTA 2006 7A. p.21. RE6 5/10,11
		29	Electric sub-station	1950	Timber fence panel enclosure	ACTA 2006 7A. p.21. RE6 5/29
OA6B Character Area 6B: North Bungalows						
		13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40	3 Bed semi detached single story buildings	1956/1957	Pebble dashed prefabricated panel construction. Pitched, tiled roof.	ACTA 2006 7. p.20. RE6 5/13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40
		42	2 Bed semi detached single story building	1957	Pebble dashed prefabricated panel construction. Pitched, tiled roof.	ACTA 2006 7. p.20. RE6 5/42
		44	4 Bed semi detached single story building	1957	Pebble dashed prefabricated panel construction. Pitched, tiled roof.	ACTA 2006 7. p.20. RE6 5/44.
		UH72	Store	u/d	Brick walls with pitched tiled roof.	ACTA 2006 7. p.20. RE6 5/UH 72

APPENDIX 11.1 (B): KNOWN ARCHAEOLOGY WITHIN THE STUDY AREA

Explanation of References used within this Gazetteer:

OA = Oxford Archaeology
 NMR = National Monuments Record
 SMR = Oxfordshire Sites & Monuments Record
 AP = Aerial Photography
 WS = Walkover Survey
 HS = Historic Sources

OA Ref. No	Feature Type	Description	Source
1001	Military Airfield	Upper Heyford Airfield.	NMR 1411508, 1416022, 1389649
1002	Listed Building	Manor Farmhouse, Fritwell Road. Grade II Listed Building	NMR 244526 SMR 11737
1003	Listed Building	Fewcott Farmhouse, Fritwell Road. Grade II Listed Building	NMR 244527
1004	Listed Building	Hunters Cottage, Somerton Road. Grade II Listed Building.	NMR 244531
1005	Listed Building	Manor Farmhouse, Somerton Road. Grade II Listed Building	NMR 244530
1006	Listed Building	Church of St Mary, Somerton Road. Grade II* Listed Building. 15th century tower, the rest of the church was rebuilt in 1864.	NMR 244528 SMR 5084, 5095
1007	Listed Structure	Headstone approximately five metres south east of chancel of Church of St Mary. Grade II Listed Structure.	NMR 244529
1008	Listed Building	Barn approximately 30 meters north of Ashgrove Farmhouse. Grade II Listed Building.	NMR 244525 SMR 13678
1009	Listed Building	Lime kiln approximately 150 metres east of lime hollow, Lower Heyford. Grade II Listed Structure.	NMR 423069, HER 18736 – MOX14251
1010	Listed Building	The Horse and groom Public House. Grade II Listed Building.	NMR 421839, HER 18669 – MOX 13662
1011	Listed Building	Troy Farmhouse, Ardley Road. Grade II Listed Building.	NMR 422083 SMR 11722
1012	Listed Building	93 Freehold Street. Grade II Listed Building.	NMR 421882
1013	Listed Building	105 Freehold Street. Grade II Listed Building.	NMR 421881
1014	Listed Building	The Mill, Mill Lane, Grade II Listed Building.	NMR 422077 SMR 5959

OA Ref. No	Feature Type	Description	Source
1015	Listed Buildings	47, 49 and 50 Freehold Street. Grade II Listed Buildings.	NMR 422046, 421884, 421883
1016	Listed Buildings	Two Trees Farmhouse and attached farm buildings. The Farmhouse is a Grade II Listed Building. The Stable Range is located c 20 metres south of the Farmhouse, and is a Grade II Listed Building. The Walled Garden is located c 40 metres south west of the farmhouse and is a Grade II Listed Building. The Barn is located c 10m south east of the farmhouse and is a Grade II Listed Building. The Cart shed is c 50m south of the Farmhouse and is a Grade II Listed Building. The Farm building is c 30m south east of the Farmhouse and is a Grade II Listed Building	NMR 423161, 423165, 423166, 423162, 423164, 423163 HER 18741 – MOX 12963, 18740 – MOX13691, 18744 – MOX13692, 18743 – MOX14268, 18745 – MOX14518, 18742 – MOX14730
1017	Listed Buildings	Manor Farmhouse, Church Walk. Grade II Listed Building The Granary is c30m south east of the Farmhouse and a Grade II Listed Building.	NMR 423071, 423072, 449500
1018	Listed Building	Church of St Mary, Church Walk. Grade II* Listed Building.	NMR 423070
1019	Listed Building	Odd Stones, High Street. Grade II Listed Building.	NMR 423151
1020	Listed Building	15-22 High Street. Grade II Listed Buildings.	NMR 423148, HER 17158 – MOX 13689
1021	Listed building	Mudginwell Farmhouse. Grade II Listed Building.	NMR 423155, HER 18739 – MOX 13748
1022	Listed Building	Rose Cottage, High Street. Grade II Listed Building.	NMR 423074, HER 18737 – MOX14517
1023	Listed Structure	Bridge c 500m north of Allen's Lock. Grade II Listed Building	NMR 423167
1024	Historic Park	Middleton Park. Grade II Listed Park. 18th-19th century landscape park.	NMR 4063
1025	Cropmarks	Cropmarks of a probable prehistoric enclosed settlement site.	NMR 1076790 SMR 12327
1026	Maze	A medieval turf maze at Troy farm, may be 16th century in date.	NMR 338877 SMR 4313
1027	Earthwork	Iron Age earthwork known as Aves Ditch running in a north-south alignment from Kirtlington to Fritwell. Later utilised as a Roman Road, known as either Wattle Bank, Ash Bank or Margary 161.	NMR 975117 SMR 8925
1028	Cropmarks	A banjo enclosure visible as a cropmark on APs. Internal features including a possible hut circle are also visible.	NMR 1378689 SMR 12166
1029	Cropmarks	A circular enclosure visible as cropmarks on APs. It has a well-defined ditch which broadens either side of the enclosure's west facing entrance. A later prehistoric date seems plausible but anything more precise is speculative on present evidence	NMR 1378696
1030	Railway	The Aynho and Ashendon railway was built in 1910 to bypass Oxford.	NMR 1363571
1031	Archaeological Investigation	An evaluation at the A43:M40-B4031 improvement carried out by Wessex Archaeology in 1993. A Mesolithic lithic implement was recovered near to Ardley.	NMR 1211493

OA Ref. No	Feature Type	Description	Source
1032	Archaeological Investigation	Evaluation carried out on Orchard Road in 1988 by Oxford Archaeological Unit. Eleven trenches were excavated, revealing a late medieval/post-medieval lynchet field boundary.	NMR 454120
1033	Cropmarks	Part of sub rectangular ditched enclosure of uncertain date is visible as a cropmark on APs.	NMR 1378694
1034	Cropmarks	Cropmarks remain of a large sub-circular enclosure comprising an outer pair of concentric ditches and a third inner concentric ditch circuit. There is an entrance gap on the western side. In the southwest of the inner enclosure is a cropmark of a large circular pit 30m in diameter. Immediately outside the inner enclosure is a small, incomplete single ditched curvilinear enclosure 15m in diameter which may represent a hut circle. This feature is not within the study area but is deemed significant to the EIA.	NMR 336910
1035	Earthworks	Earthworks marked on an Ordnance Survey map of 1833, possibly Roman	NMR 338881 SMR 16844
1036	Site of Building	Site of railway station opened in 1910 and closed in 1963.	NMR 502168 SMR 12436
1037	Cropmarks	An Iron Age "banjo enclosure" visible as cropmarks. The site lies immediately outside the fence of Upper Heyford airfield. Measuring c 56 by 68m, it faces east, the ditch defined approach running some 75 metres towards a former watercourse.	NMR 1378602 HER 17446 – MOX23329
1038	Cropmarks	A ring ditch 14 m across is visible as a cropmark on APs. It lies among a series of linear and rectilinear cropmarks which appear to represent part of a ditched field system of presumed later prehistoric date and which appears to respect the enclosure	NMR 1378632 (part of 17448 – MOX23331)
1039	Cropmarks	A fragment of an enclosure (or, just possibly a linear feature) is visible as a cropmark on APs. A later prehistoric date is assumed on the basis of the other sites in the vicinity.	NMR 1378612
1040	Cropmarks	A complex of sub rectangular enclosures, probably representing Iron Age and/or Romano British settlement, is visible as cropmarks on APs. The complex is located adjacent to a former watercourse and covers an area circa 230 metres by 100 metres	NMR 1378617 includes HER 17447 – MOX23330
1041	Cropmarks	A large rectangular ditched enclosure is visible as cropmarks on APs. Aligned northwest southeast, the enclosure measures c 140 by 95m and appears to feature right angled corners.	NMR 1378647
1042			
1043	Inhumations	Possible early medieval inhumations, with grave goods including stirrups, found at The Leas.	NMR 338876 SMR 5915, HER 17003 – MOX 12823
1044	Cropmarks	A probable banjo enclosure visible as a cropmark on Aps – with curvilinear annexe visible.	NMR 1378688, HER 17443 – MOX23326
1045	Cropmarks	A sub circular enclosure with double ditched approach visible as a cropmark on APs	NMR 1378687
1046	Archaeological Investigation	Excavation at Aves Ditch, The Gorse carried out by Oxford University Archaeological Society in 1997 and 1998. Sectioning of the linear earthwork within The Gorse recovered Iron Age pottery from the bank and a mutilated adult burial from the bottom of the ditch.	NMR 1171850
1047	Road	Roman road extending from Hanwell to Oxford. Port Way.	NMR 974918 SMR 8926

OA Ref. No	Feature Type	Description	Source
1048	Cropmarks	Cropmarks of a probable prehistoric or Roman rectangular enclosure and linear features.	NMR 1076784, SMR 9410
1049	Building	Post-medieval chapel. Roughly cut stone in uneven courses. Gabled roof now slated.	SMR 536
1050	Archaeological Investigation	Watching Brief at land west of Two Trees Farmhouse, High Street, Upper Heyford. Carried out by John Moore Heritage Services in 1999. A post-medieval ditch and wall were found, thought to be a property boundary.	NMR 1333105, SMR EOX118, 16342
1051	Canal	Construction of the Oxford Canal was authorised in 1769 with the intention to bring coal southwards from the Warwickshire coalfield to Banbury and Oxford; it was also to provide access to the River Thames.	NMR 1340619
1052	Cropmarks	Cropmarks of a pit alignment of uncertain date.	NMR 1076788
1053	Railway Line	The Birmingham and Oxford Junction line opened between Millstream Junction, in Oxford, and Banbury in 1850, and was initially broad gauge. The rest of the line to Birmingham was a double line of mixed gauge and opened in 1852.	NMR 1361054
1054	Cropmarks	Cropmarks of a possible Prehistoric or Roman settlement site consisting of a trackway, enclosures, pits and a possible hut circle.	NMR 1076798 SMR 15970
1055	Scheduled Monument	Somerton Manor House; earthworks and remains of hall. Original house built in the early 16th century. Demolished late 18th/early 19th century. One window remains.	NMR OX152 SMR 5033
1056	Scheduled Monument	Ardley Wood Moated Ringwork. Norman sub-rectangular earthwork enclosure situated c 100m south west of Manor Farm. The monument is believed to be originally a Norman ringwork and later reused as a medieval dry moated settlement site.	NMR 28166 SMR 2526
1057	Scheduled Monument	Upper Heyford Tithe Barn. Early 15th century stone barn, substantially unaltered and in good condition.	NMR 423073, OX93, SMR 3199
1058	Cropmarks	Large rectangular enclosure. Enclosure of c 110x70m with several subdivisions. South boundary of this enclosure appears to intersect a small banjo enclosure.	SMR 12247
1059	Milestone	Post-medieval milestone. Type T6.	SMR 10058
1060	Findspot	Romano British pottery sherds found in 1973 while locating the Agger of a Romano British road whilst surveying in mid north Oxfordshire.	SMR 3072
1061	Earthworks	Earthworks showing a medieval/Post-medieval shrunken village. The earthworks span three adjoining fields. Three aspects (i) outline of large building and two house platforms with hollow way intervening. (ii) Two hollow ways continuing the line of the existing roads. (iii) series of platforms and crofts where one cottage has been removed since the 1950s	SMR 9015
1062	Listed Building	Post-medieval Grade III Listed Building. Former Rectory, built by 1665, and enlarged in 1860.	SMR 2752
1063	Fishponds	Medieval/Post-medieval fishponds. two ponds with intervening causeway or dam shown in 1955. Larger pond to the west called The Fish Pond. Smaller pond to the east called The Horse Pond, now mostly infilled.	SMR 1350
1064	Findspot	Brooch (penannular). Probably 14th century. Found in 1992.	SMR 14375
1065	Building	All Saints Church. Built in 1870 at a cost of £900.	SMR 5093
1066	Findspot	Medieval iron dagger found by metal detectorists. OMS acc no 86.302	SMR 13893

OA Ref. No	Feature Type	Description	Source
1067	Cropmarks	Cropmarks of a hexagonal enclosure. Identified by R Hingley in 1979.	SMR 12328
1068	Pond	Crowfoot pond seen in the OS photo survey of 1947	SMR 11723
1069	Quarry	Post-medieval quarry, c 130m east of Port Way, seen on the OS photo survey of 1947	SMR 11729
1070	Quarry	Post-medieval quarries, seen on the OS photo survey of 1947.	SMR 11719
1071	Cropmarks	Bronze Age barrow. Single circle cropmark with a spot near the centre. The area is now affected by housing so the barrow is probably destroyed.	SMR 7875
1072	Archaeological Investigation	Watching Brief carried out by Oxford Archaeological Unit in August 1994. Four E-W ditches with Middle Iron Age pot suggested nearby settlement.	SMR 15815
1073	Earthwork	Medieval fishpond across west facing valley.	SMR 5968
1074	Listed Building	Post-medieval canal bridge. Grade II Listed. Elaborate brick bridge spanning river and canal, finished by 1790 when canal opened. Bridge number 203. Foundations of earlier structure may have survived.	SMR 5939
1075	Lock	Canal lock, Allens Lock. Shown on the 1881 OS map.	SMR 215
1076	Bridge	18th century canal bridge over Allens lock. This bridge has no towpath suggesting that a pre-canal structure may have been adapted for canal use in the 1780s.	SMR 5940
1077	Building	Post-medieval Rectory farm, High Street. Three bay, 17th century farmhouse	SMR 10991
1078	Site of Building	Post-medieval rectory, 17th/18th century. A medieval rectory was rebuilt here in 1696, and remained until the present rectory was built in 1865.	SMR 5938
1079	Building	Stone built Wesleyan Chapel with the date 1867 on the altar.	SMR 3276
1080			
1081	Earthworks	Medieval shrunken village. Several platforms and banks in and around the village indicate sites of former farmsteads, especially east of the church.	SMR 5947
1082	Site of Building	Water Mill shown on the 1881 OS map. Pulled down in c 1910.	SMR 216
1083	Cropmarks	Irregular cropmarks on each side of Aves Ditch. Possibly prehistoric but possibly natural.	SMR 11553
1084	Structure	Drystone wall on part of the eastern boundary of accommodation area. Shown as boundary on 1st edition OS map of 1885.	HS/WS
1085	Archaeological Investigation	A series of evaluations carried out by John Samuels Archaeological Consultants in May 1999. The results indicated that there had been considerable ground disturbance over much of the site. There was evidence to suggest the survival of some archaeological remains at the western end of the former airfield. 1) – trenches 5 and 6 contained undated linear features suggesting archaeological potential 2) No features found here 3) Any archaeology here would have been destroyed by previous construction	SMR EOX1762-6,

OA Ref. No	Feature Type	Description	Source
1086	Cropmarks	Series of cropmarks seen on AP RAF/106G/UK/1488 RP 3005 9-May-46. Located to the south of Troy Farm they appear to be a series of boundary ditches and incomplete rectilinear enclosures.	AP HER 17444 – MOX23327
1087	Cropmarks	Series of cropmarks seen on AP RAF/542/1 F21 34 4-Aug-54. Located to the east of Somerton, they appear to be a series of three sub circular enclosures and a ditch.	AP
1088	Cropmarks	Series of cropmarks seen on AP SP5124/1 NMR 4634 38 2-Jun-90. Located to the south of the airfield, they appear to be a sub rectangular enclosure.	AP
1089	Field System	Field boundaries first shown on the 1839 Tithe Map of the parish of Ardley. The majority of the field boundaries are shown on all subsequent maps including the OS revision of 1923, with the exception of one NW-SE aligned footpath which was shown only on the 1839 map.	HS
1090	Field System	Field boundaries first shown on the Upper Heyford Inclosure Map of 1842.	HS
1091	Field System	Field boundaries first shown on the 1st Edition Ordnance Survey Map of 1885.	HS
1092	Field System	Field boundaries first shown on the 2nd Edition Ordnance Survey Map of 1900.	HS
1093	Field System	Field boundaries first shown on the 3rd revision of the OS map, 1923	HS
1094	Quarry	Old Quarry first shown on the 1st edition map of 1885. Still present by 1923 OS map	HS
1095	Quarry	Old Quarry first shown on the 1st edition map of 1885. Still present by 1923 OS map	HS
1096	Former Building	Building first shown on the 1885 OS map labelled The Tower. Set within an enclosed piece of land. By the 1900 2nd edition, the large building has gone and there is only a smaller building present.	HS
1097	Former Buildings	Group of buildings first shown on the 1st edition map of 1885. Still present by 1923 OS map	HS
1098	Former Building	Hall Farm first shown on the 1839 Tithe map of Ardley. Still present by 1923 OS map	HS
1099	Former Building	Building entitled Field barn first shown on the 1st edition map of 1885. Still present by 1923 OS map	HS
1100	Well	Well first shown on the 1st edition OS map of 1885. Still present by 1923 OS map	HS
1101	Buildings	Military buildings within Upper Heyford built c 1926. No longer extant.	HS
1102	Buildings	Military buildings within Upper Heyford built by 1939. No longer extant.	HS
1103	Buildings	Military buildings within Upper Heyford built by 1945. No longer extant.	HS
1104	Conservation Area	Somerton	HS
1105	Conservation Area	Ardley	HS
1106	site	Earthwork seen on 1st edition 1" map associated with Aves Ditch	HS
1107	Archaeological investigation	Work carried out for Thames Water along pipeline; route followed lengths of both Akeman St and Aves Ditch. General scatter of artefacts present in area, but no concentrations indicative of buried archaeological deposits – mainly post-med in date (Cotswold Archaeology 2004).	HER EOX1536

OA Ref. No	Feature Type	Description	Source
1108	Watching Brief & Evaluation & Magnetometer	<p>1) Watching brief on 8 holes to replace power cable poles close to Aves ditch – no archaeology observed though colluvium present (OA 2009)</p> <p>2) Work carried out for Thames Water along pipeline – 3 Iron Age farmsteads were excavated in the vicinity of Aves Ditch – remains included pits and ditches mostly of Middle IA date and extending into L IA. Aps and geophysics indicate tow of the settlements were enclosed (Cotswold Archaeology 2009)</p> <p>Magnetometer survey. Carried out ahead of Thames Water pipeline by Archaeological Surveys Ltd (Arch Sols 2005)</p>	<p>HER EOX2480</p> <p>HER EOX2533</p> <p>HER EOX2084</p>
1109	Conservation Area	Rousham Conservation Area which includes Upper Heyford historic core including medieval sunken village earthworks and site of medieval parsonage and Lower Heyford.	HER DOX 17158
1110		Number not used	
1111	Cropmark	Banjo enclosure and associated antenna visible as cropmarks on NMR aerial photos	HER 17442 – MOX23325
1112	Excavation	Excavation recorded a large NW/SE aligned late IA boundary ditch with tow groups of mid to late IA pits to the west side of it and another perpendicular ditch to the east (Cotswold Archaeology 2009).	HER 26107 – MOX23469
1113	Geophysics and evaluation	Oa evaluation and geophysics – west end – earlier ploughsoils and ridge and furrow sealed by modern made ground which overlay probable Iron Age ring ditches (OA 2007)	OA
1114	Evaluation	OA geophysics – east end – evidence for positive and negative linear anomalies found – possibly to do with previous agricultural use.	OA