



- Legend**
- Discharge Area's Used**
- Discharge Area 1
 - Discharge Area 2
 - Discharge Area 4
 - Discharge Area 6
 - Discharge Area 7
 - Discharge Area 8
 - Discharge Area 15
 - Discharge Area 16
 - Discharge Area 17
- Discharge Area's Not Used**
- Discharge Area 3
 - Discharge Area 5
 - Discharge Area 9
- Well Monitored by VFLI - Weekly During Discharge to That Area**
- Well Dry - Watching Brief by VFLI**
- Well Monitored by Watermans**
- Percolation Test Locations**
- Pre & Post Remediation Soil Sample Locations (Reference Numbers Are The Same - See Date Sampled)**
- Area's 3, 5 & 9 - Pre Remediation Soil Sample Locations Only**

F	Samples Now Pre & Post Remediation	MRG	16-01-12
E	Pol 25b renamed 25a & vice versa	MRG	14-11-11
D	Discharge Area 10 Removed	MRG	18-10-11
C	Discharge Areas 10, 15, 16 & 17 Added	MRG	13-10-11
B	Soil Samples Locations Added for Zones 1 & 2	MRG	20-09-11
A	Percolation Locations Added	MRG	07-09-11
	FIRST ISSUE		19-08-11

Rev.	Description	Revised By	Date
------	-------------	------------	------

Vertase F.L.I.

- Bristol Head Office: Tel: 01275 397600 Fax: 01275 397601
- Sheffield Office: Tel: 01246 813289 Fax: 01246 812983
- Hertford Office: Tel: 01992 535757 Fax: 01992 535858
- Manchester Office: Tel: 01614 372708 Fax: 01614 376300

email: info@vertasefli.co.uk
www.vertasefli.com

Site Address: Upper Heyford	Rev: F
--------------------------------	------------------

Title: Discharge Areas - Final

Client: Upper Heyford LP

Drawn: MRG	Checked: LH	Approved: LH
------------	-------------	--------------

Dwg: 2862_11	Contract: 2862	Scale: 1:4000
--------------	----------------	---------------