

Appendix D – Example Photographs



Photograph 13: POL 2C - Pre-condition photograph. Taken during tank sampling and inspection



Photograph 250: POL 23B - Tank condition after clean and degas



Photograph 246: POL 23B - Tank condition after clean and degas



Photograph 275: POL 25C - Pre-condition



Photograph 277: POL 25C - Tank condition after clean and degas



Photograph 367: Water treatment plant - POL22



Photograph 285: AST 3 - Pre-condition



Photograph 375: Batching plant



Photograph 377: Batching plant



Photograph 380: Batching plant



Photograph 381: POL tank chute filling



Photograph 384: POL tank chute filling



Photograph 54: POL 3B - Tank filled including concrete weathering cap



Photograph 389: Pump-over grout filling of Type 1 tank



Photograph 388: Pump-over grout filling of Type 1 tank