

## Photographic record



**Photograph 1** - Yew trees T1 and T2 just to the left on centre on the west boundary of the front garden. The crown of Holly tree T3 is to the far left of the photograph.



**Photograph 2** – Looking up into the canopies of Yew trees T1 and T2.





**Photograph 3** – Holly tree T3 above the entrance steps.



**Photograph 4** – The bulge in the stone wall caused by root pressure from Holly tree T3.





**Photograph 5** – Holly tree T4 to the right of photograph and Silver Birch tree T5 to the left of centre.



**Photograph 6** – The crown of Silver Birch tree T5 spreading over the adjacent dwelling on Main Street.



**Photograph 7** – Pear tree T6 leaning out from the base of the stone wall.



**Photograph 8** – The stem of Pear tree T6 right against the base of the stone wall.

