

Tree Category A - High Quality

A Category - Hedgerow, Group, Woodland

Tree Category B - Moderate Quality


B Category - Hedgerow, Group, Woodland

Tree Category C - Low Quality

C Category - Hedgerow, Group, Woodland

Tree Category U - Unsuitable for Retention

Root Protection Area to BS:5837:2012



Revisions: Date
A • First issue 10/10/2014
B • Village Centre trees updated 05/01/2015 C • All trees updated to show current situation 11/03/2015
D • Trees 1405-1493 added 02/07/2015
E • Updated topo & phase 7 area updated 25/09/2015
F • T31-G33 & T204-T207 & G203 resurveyed as single trees 09/12/2015
G • T1334 - T1341 & T1362 & 11/01/2016 H • Tree data updated on land south of camp road and around tennis courts Trees (957/958/959/960/965/966) restored to plan 23/09/2016

J • Phase 1 Trees amended (G17, T18, G20, G21) 10/10/2016 Phase 8 area trees reviewed and amended - removals and category changes L • Revised survey recieved from West Waddy 31/01/2018

**Note:** The original of this drawing was produced in colour - a monochrome copy should not be relied upon.

#### Heyford Park


#### Tree Survey & Constraints Plan


Drawing Ref: **D.0341\_37-L (Sheet 11 of 16)** 

Client : Dorchester Group

1 : 1000 **@** A1 Date : 31/01/2018 Drawn by : DP/JS/AD/West Waddy Checked by : West Waddy Pegasus Environmental

| T 01285 641717 | F 01285 642348 | www.pegasuspg.co.uk |







Tree Category A - High Quality

A Category - Hedgerow, Group, Woodland

Tree Category B - Moderate Quality B Category - Hedgerow, Group, Woodland







Revisions: Date						
A	•	First issue	10/10/2014			
В	•	Village Centre trees updated	05/01/2015			
С	•	All trees updated to show current situation	11/03/2015			
D	•	Trees 1405-1493 added	02/07/2015			
Е	•	Updated topo & phase 7 area updated	25/09/2015			
F	•	T31-G33 & T204-T207 & G203 resurveyed as single trees	09/12/2015			
G	•	T1334 - T1341 & T1362 & T1198 resurveyed	11/01/2016			
Н	•	Tree data updated on land south of camp road and around tennis courts	22/06/2016			
I	•	Trees (957/958/959/960/965/966) restored to plan	23/09/2016			
J	•	Phase 1 Trees amended (G17, T18, G20, G21)	10/10/2016			
K	•	Phase 8 area trees reviewed and amended - removals and category changes	16/02/2017			

Revised survey recieved from West Waddy 31/01/2018

**Note:** The original of this drawing was produced in colour - a monochrome copy should not be relied upon.

## Heyford Park

#### Tree Survey & Constraints Plan

Drawing Ref: **D.0341\_37-L (Sheet 12 of 16)** Client : Dorchester Group


1 : 1000 **@** A1 Date : 31/01/2018 Drawn by : DP/JS/AD/West Waddy Checked by : West Waddy Pegasus Environmental





| T 01285 641717 | F 01285 642348 | www.pegasuspg.co.uk | © Copyright Pegasus Planning Group Ltd. © Crown copyright, All rights reserved. 2015 emapsite Licence number 0100031673. Ordnance Survey Copyright Licence number 100042093 | Promap Licence number 100020449 | Pegasus Environmental is part of Pegasus Planning Group Ltd. Drawing prepared for planning. Any queries to be reported to Pegasus for clarification
















Revi	isior	Date	
Α	•	First issue	10/10/2014
В	•	Village Centre trees updated	05/01/2015
С	•	All trees updated to show current situation	11/03/2015
D	•	Trees 1405-1493 added	02/07/2015
Е	•	Updated topo & phase 7 area updated	25/09/2015
F	•	T31-G33 & T204-T207 & G203 resurveyed as single trees	09/12/2015
G	•	T1334 - T1341 & T1362 & T1198 resurveyed	11/01/2016
Н	•	Tree data updated on land south of camp road and around tennis courts	22/06/2016
I	•	Trees (957/958/959/960/965/966) restored to plan	23/09/2016
J	•	Phase 1 Trees amended (G17, T18, G20, G21)	10/10/2016
K	•	Phase 8 area trees reviewed and amended - removals and category changes	16/02/2017
L	•	Revised survey recieved from West Waddy	31/01/2018


**Note:** The original of this drawing was produced in colour - a monochrome copy should not be relied upon.

## Heyford Park


#### Tree Survey & Constraints Plan

Drawing Ref: **D.0341\_37-L (Sheet 13 of 16)** Client : Dorchester Group

1 : 1000 **@** A1 Date : 31/01/2018 Drawn by : DP/JS/AD/West Waddy Checked by : West Waddy Pegasus Environmental



| T 01285 641717 | F 01285 642348 | www.pegasuspg.co.uk | © Copyright Pegasus Planning Group Ltd. © Crown copyright, All rights reserved. 2015 emapsite Licence number 0100031673. Ordnance Survey Copyright Licence number 100042093 | Promap Licence number 100020449 | Pegasus Environmental is part of Pegasus Planning Group Ltd. Drawing prepared for planning. Any queries to be reported to Pegasus for clarification



Tree Category A - High Quality

A Category - Hedgerow, Group, Woodland

Tree Category B - Moderate Quality


B Category - Hedgerow, Group, Woodland

C Category - Hedgerow, Group, Woodland

Tree Category C - Low Quality

Tree Category U - Unsuitable for Retention

Root Protection Area to BS:5837:2012



Revisions:

A First issue
10/10/2014
B Village Centre trees updated
C All trees updated to show current situation
D Trees 1405-1493 added
C Updated topo & phase 7 area updated
C Updated topo & phase 7 area updated
C Tall-G33 & T204-T207 & G203 resurveyed as single trees
C T1334 - T1341 & T1362 & T1/01/2016
C Tree data updated on land south of camp road and around tennis courts
C Trees (957/958/959/960/965/966) restored to plan
C Phase 8 area trees reviewed and amended - removals and category changes
C Revised survey recieved from West Waddy

Date
10/10/2015
11/03/2015
11/03/2015
11/03/2015
11/03/2015
11/03/2016
11/03/2016
12/06/2016
13/09/2016
14/00/2017

**Note:** The original of this drawing was produced in colour - a monochrome copy should not be relied upon.

#### Heyford Park

# Tree Survey & Constraints Plan

Drawing Ref: **D.0341\_37-L (Sheet 14 of 16)**Client : **Dorchester Group** 

1 : 1000 **@** A1 Date : 31/01/2018 Drawn by : DP/JS/AD/West Waddy Checked by : West Waddy





Tree Category A - High Quality

A Category - Hedgerow, Group, Woodland

Tree Category B - Moderate Quality


B Category - Hedgerow, Group, Woodland

Tree Category C - Low Quality

C Category - Hedgerow, Group, Woodland

Tree Category U - Unsuitable for Retention

Root Protection Area to BS:5837:2012



Revision	Date	
Α •	First issue	10/10/2014
В •	Village Centre trees updated	05/01/2015
C •	All trees updated to show current situation	11/03/2015
D •	Trees 1405-1493 added	02/07/2015
E •	Updated topo & phase 7 area updated	25/09/2015
F •	T31-G33 & T204-T207 & G203 resurveyed as single trees	09/12/2015
G •	T1334 - T1341 & T1362 & T1198 resurveyed	11/01/2016
Н •	Tree data updated on land south of camp road and around tennis courts	22/06/2016
1 •	Trees (957/958/959/960/965/966) restored to plan	23/09/2016
J •	Phase 1 Trees amended (G17, T18, G20, G21)	10/10/2016
К •	Phase 8 area trees reviewed and amended - removals and category changes	16/02/2017
L •	Revised survey recieved from	31/01/2018

**Note:** The original of this drawing was produced in colour - a monochrome copy should not be relied upon.

#### Heyford Park

#### Tree Survey & Constraints Plan

Drawing Ref: **D.0341\_37-L (Sheet 15 of 16)** 

Client : Dorchester Group

1 : 1000 **@** A1 Date : 31/01/2018 Drawn by : DP/JS/AD/West Waddy Checked by : West Waddy





Tree Category A - High Quality

A Category - Hedgerow, Group, Woodland

Tree Category B - Moderate Quality


B Category - Hedgerow, Group, Woodland

Tree Category C - Low Quality

C Category - Hedgerow, Group, Woodland

Tree Category U - Unsuitable for Retention

Root Protection Area to BS:5837:2012



Revisions:

A • First issue 10/10/2014
B • Village Centre trees updated 05/01/2015
C • All trees updated to show current situation 11/03/2015
D • Trees 1405-1493 added 02/07/2015
E • Updated topo & phase 7 area updated 7 sesurveyed as single trees 11/01/2015
G • T131-G33 & T204-T207 & G203 resurveyed as single trees 11/01/2016
H • Tree data updated on land south of camp road and around tennis courts 12/06/2016
I • Trees (957/958/959/960/965/966) restored to plan 23/09/2016
J • Phase 1 Trees amended (G17, T18, G20, G21) 10/10/2016
K • Phase 8 area trees reviewed and amended - removals and category changes 16/02/2017
L • Revised survey recieved from West Waddy 31/01/2018

**Note:** The original of this drawing was produced in colour - a monochrome copy should not be relied upon.

#### Heyford Park

## Tree Survey & Constraints

Drawing Ref: **D.0341\_37-L (Sheet 16 of 16)** 

Client : Dorchester Group

1 : 1000 **@** A1 Date : 31/01/2018 Drawn by : DP/JS/AD/West Waddy Checked by : West Waddy

